

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20007003/UPS3Q2

Date: 12/08/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0002627_01
Claimant Vehicle No :	FBH6416D	Insured Vehicle No :	SLC7013J
Date of Loss:	24/06/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0001168

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBH6416D	Engine No:	PC40E2305641
Make & Model:	HONDA CBR600RR, 599cc	Chassis No:	JH2PC40C8CK500625
Reg. Date:	11/06/2012 (Man. Year: 2012)	Odometer:	56731 km
Colour:	White		
Engine Capacity:	599 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120-70Z R17	Rear Tyre Size:	180-55Z R17
Front Left Side:	Battlax 5 mm	Rear Left Side:	Battlax 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,536.00	4,302.00	2,234.00	34.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,290.00	760.00	530.00	41.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,826.00	5,062.00	2,764.00	35.32
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	7,826.00	4,000.00	3,826.00	48.89
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	06/07/2020	
Date Inspected:	06/07/2020 Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 12 Aug 2020)	
Parts:	N/A	HONDA CBR600RR 599cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBH6416D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT SIGNAL -L/R/H	Cracked	340.00 FL	*310.00 FL
2	1		*HEAD LAMP ASSY	Scratched	650.00 FL	*485.00 FL
3	1		*FRONT FAIRING	Cut	780.00 FL	*780.00 FL
4	1		*HANDLE BAR -R/H	Bent	260.00 FL	*260.00 FL
5	1		*BRAKE PUMP ASSY W/BRAKE LEVER -R/H	Cut	280.00 FL	*280.00 FL
6	1		*THROTTLE CABLE	Cut	95.00 FL	*95.00 FL
7	1		*MIRROR -R/H	Scratched	165.00 FL	*165.00 FL
8	1		*HEAD LAMP SIDE COVER -R/H MATT BLAKE	Cut	55.00 FL	*55.00 FL
9	1		*FRONT SIDE FAIRING UPPER -R/H	Cut	750.00 FL	*750.00 FL
10	1		*FRONT SIDE FAIRING CENTER -R/H	Cut	650.00 FL	*650.00 FL
11	1		*FRONT SIDE FAIRING LOWER -R/H	Cut	780.00 FL	*780.00 FL
12	1		*REAR SIGNAL -R/H	Scratched	170.00 FL	*170.00 FL
13	1		*RIDER FOOTREST -R/H	Serviceable	90.00 FL	*- FL
14	1		*BRAKE PEDAL	Serviceable	160.00 FL	*- FL
15	1		*PILLIONS FOOTREST-R/H	Serviceable	90.00 FL	*- FL
16	1		*PILLIONS FOOTREST BRACKET-R/H	Not Necessary	180.00 FL	*- FL
17	1		*FRONT SIDE INNER COVER CENTRE -R/H	Not Necessary	55.00 FL	*- FL
18	1		*RIDER FOOTREST BRACKET R/H	Not Necessary	160.00 FL	*- FL
19	1		*RADIATOR ASSY	Not Necessary	1,050.00 FL	*- FL
20	1		*FRONT FAIRING BRACKET	Repair	280.00 FL	*- FL
21	1		*BEARING CONE	Not Necessary	80.00 FS	*- FS
22	1		*FORK REPAIR	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,240.00	4,780.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	704.00	478.00
Total Parts (\$\$)	6,536.00	4,302.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	80.00	80.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	480.00	280.00
4	TO RE-SPRAY PAINTING	New	650.00	400.00
Gross Labour Cost (\$\$)			1,290.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >