

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

6-Jul-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6988 A

1 pc	Boot lid X R	\$	1,119.00
1 pc	Boot lid lock X	\$	99.00
1 pc	Bootlid lock cable X	\$	35.00
1 pc	Bootlid striker X	\$	21.00
1 pc	Bootlid emblem / M	\$	27.00
1 pc	Bootlid CRDi / n/c	\$	29.00
1 pc	Boot lid rubber weatherstrip / CR4	\$	96.00
1 pc	Boot lid lower garnish X R	\$	290.00
2 pcs	Bootlid hinges @ \$66.00 X R	\$	132.00
2 pcs	Rear license plate lamp @ \$30.00 X	\$	60.00
2 pcs	Bootlid hinge torsion bar @ \$33.00 X	\$	66.00
1 pc	Bootlid inner trim X	\$	190.00
1 pc	End panel / n/c	\$	250.00
1 pc	End panel inner garnish ?	\$	74.00
1 pc	Rear bumper / n/c	\$	696.00
1 pc	Rear bumper lower cover / CR4	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 / R	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ?	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
1 / 2 pcs	Rear bumper reflector n/s & o/s @ \$46.00 (R4) ?	\$	92.00
2 pcs	n/s & o/s tail lamp @ \$421.00 X	\$	842.00
2 pcs	n/s & o/s reflector @ \$350.00 X	\$	700.00
		\$	5,981.00
		Less 10%	\$ 598.10
		\$	5,382.90

S/NETT

1 set	Rear bumper clips / n/c	\$	48.00 J
1 set	End panel inner garnish clips / n/c	\$	30.00 19
1 set	Bootlid inner trim clips X	\$	52.00
1 set	Bootlid lower garnish clips X	\$	60.00
1 set	Bootlid stickers X	\$	100.00
1 set	Reverse sensor / SL4	\$	280.00 J

6-Jul-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6988 A

Sundry

\$ 50.00 30

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ 120.00 30

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ 180.00 50

To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, including knock-out, straighten, repair, reshape and adjust of the floorboard etc

\$1,200.00 700

To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel

\$ 1,000.00 600

To apply rustproofing on the repaired and replaced panels.

\$ 200.00 30

\$ 8,702.90

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Steve (LKK)
8322 8813

ML ML
6/7/20, 2.45pm

4 dgs

L/S

My AC sig

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: