

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: NO 78, SHENTON WAY, #07-16,
S(079120)

Telephone: 64193000

Fax: 68357416

Email: assignments@lkkauto.com

Make/ Model : HYUNDAI SANTA FE

Date: 06.07.2020

Chassis No : KMHS381DSL0239290

Vehicle No: SMQ2585Y

Date/Time of Accide 23.06.2020/ 0755

Date of Reg: 05.11.2019

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE FOR ONE	FINAL PRICE \$
1	TAILGATE <i>Reps</i>	1	\$ 2,327.00	\$ X 2,327.00
2	TAILGATE OUTER GARNISH <i>old new</i>	1	\$ 298.70	\$ X 298.70
3	TAILGATE LOGO <i>New</i>	1	\$ 102.50	\$ ✓ 102.50
4	TAILGATE "SANTA FE" EMBLEM <i>3 new</i>	1	\$ 98.70	\$ ✓ 98.70
5	TAILGATE "HTRAC" EMBLEM <i>3 new</i>	1	\$ 89.50	\$ ✓ 89.50
6	TAILGATE LAMPS <i>3 new</i>	2	\$ 485.20	\$ + 970.40
7	TAILGATE WEATHERSTRIP <i>3 new</i>	1	\$ 265.80	\$ + 265.80
8	TAILGATE INNER TRIM <i>3 new</i>	1	\$ 402.80	\$ + 402.80
9	TAILAMPS <i>old new</i>	2	\$ 582.60	\$ + 1,165.20
10	REAR END PANEL <i>Reps</i>	1	\$ 795.20	\$ X 795.20
11	REAR END PANEL TOP GARNISH <i>old new</i>	1	\$ 245.30	\$ + 245.30
12	REAR BUMPER UPPER <i>3 Deland</i>	1	\$ 502.20	\$ ✓ 502.20
13	REAR BUMPER LOWER <i>3 Deland</i>	1	\$ 592.10	\$ ✓ 592.10
14	REAR BUMPER REINFORCEMENT <i>cut d</i>	1	\$ 345.70	\$ ✓ 345.70
15	REAR BUMPER LOWER SKID PLATE <i>Del d</i>	1	\$ 235.80	\$ ✓ 235.80
16	REAR BUMPER SIDE RETAINERS <i>New</i>	2	\$ 92.50	\$ ✓ 185.00
17	REAR BUMPER SIDE CHROME GARNISH <i>old new</i>	2	\$ 205.80	\$ 205.80 411.60
18	REAR BUMPER LOWER CENTRE MOLDING <i>old new</i>	1	\$ 98.70	\$ ✓ 98.70
19	REAR BUMPER TOWING COVER <i>old new</i>	1	\$ 58.20	\$ + 58.20
20	REAR BUMPER REFLECTORS <i>old new</i>	2	\$ 378.60	\$ 378.60 757.20
21	REAR REVERSE SENSORS <i>2 pieces changed</i>	4	\$ 235.60	\$ 471.20 942.40
22	REAR EXHAUST TIP GARNISH <i>old new</i>	1	\$ 165.80	\$ X 165.80
Total List Price Cost				\$ 11,055.80

PARTS DISCOUNT 20%

\$ 8,844.64

330580

264464

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR BUMPER CLIPS <i>Nu</i>	1 SET	\$ 30.00	\$ 30.00 ✓
2	END PANEL SEALANTS <i>new</i>	2	\$ 80.00	\$ 80.00 ✗
3	WINDSCREEN SEALANTS <i>new</i>	2	\$ 80.00	\$ 80.00 ✗
4	REAR REVERSE SENSORS <i>Reps</i>	1 SET	\$ 250.00	\$ 250.00 ✗
5	REAR NUMBER PLATE WITH CASING <i>Nu</i>	1 SET	\$ 50.00	\$ 50.00 ✗
Total Special Nett Items				\$ 490.00
Labour Works/ Panel Beating Related Works				
Job Scope				Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS				\$ 1,800.00
Spray Painting				Quotation
Job Scope				Quotation
TO RESPRAY AFFECTED AREAS				\$ 1,600.00
Others Cost (Accident Repair Related Expenses)				Quotation
Job Scope				Quotation
TO TUFFCOAT AFFECTED AREA				\$ 50 200.00
TO REMOVE AND REPLACE SENSORS AND DISTANCE SETTLING				\$ 50 150.00
TO CONDUCT WIRING CHECK ON REAR TAILAMPS				\$ 30 120.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY				\$ ✗ 150.00
Total Others Cost				\$ 620.00
GRAND TOTAL				\$ 13,354.64

CAS GARAGE PTE LTD
 UEN 201828067M
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allan@casgarage.sg
 Fax : 6509 9501

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3604.64

L/S: 2850 ✓

Admin Lj
 1/8 07/07/20

03 Days

930

30

400

400