



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Ref: CC4/ASM20007025/Bps3q2 Date: 01/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJM 1005T	Veh. Inspected	SMK 5676E	
Policy No.	GA523082	Coverage (\$)	0.00	
Claim No.	S0M02QAP	Excess (\$)	0.00	
Assign From		Assign Date	07/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS ES300H	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTHB21B1502033514	Colour	RED	
Odometer	157147 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45 R18	BRIDGESTONE	6 mm	
L/H Front Tyre	235/45 R18	BRIDGESTONE	6 mm	
R/H Rear Tyre	235/45 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	235/45 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/03/2020	Inspection Date	09/07/2020	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	