

Not Authored
L/Smp &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C

AAD2007-006

06 JUL 2020

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5980C

VF1ABL15AUC281511

RENAULT

LATITUDE

2.7.2020

TOKIO MARINE

23-03-15

PART		LIST	
1	BUMPER COVER REAR	\$	B ₁ 561.70 ✓
1	BUMPER LOWER REAR	\$	CM 411.90 ✓
1	BUMPER BRACKET CTR REAR	\$	S ₂ 98.10 X
1	BUMPER BRACKET SIDE RH REAR	\$	D ₁ 82.10 ✓
1	BUMPER RETAINER RH REAR	\$	D ₁ 59.80 ✓
1	BUMPER REFLECTOR RH	\$	B ₂ 16.60 ✓
1	BUMPER BRACKET SIDE LH REAR	\$	S ₂ 80.80 X
1	BUMPER RETAINER LH REAR	\$	S ₂ 54.20 X
1	BUMPER REFLECTOR LH	\$	S ₂ 16.60 X
1	BUMPER BEAM REAR	\$	B ₂ 547.80 ✓
1	BUMPER BEAM BRACKET LH REAR	\$	N 114.50 X
1	BUMPER BEAM BRACKET RH REAR	\$	N 100.90 X
1	BUMPER BLOCK RH REAR	\$	S ₂ 76.50 X
1	BUMPER HARNESS REAR	\$	S ₂ 301.10 X
1	OUTER PANEL REAR (End Panel)	\$	B ₂ 745.80 ✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	S ₂ 404.56 X
1	TAILLAMP RH	\$	CM 401.40 ✓
1	TAILLAMP PANEL RH	\$	B ₂ 401.40 ✓
1	TAILLAMP LH	\$	S ₂ 401.40 X
1	TAILLAMP PANEL LH	\$	N 401.40 X
1	BOOT REAR	\$	B ₂ 1,677.20 ✓
1	BOOT FINISHER	\$	S ₂ 344.70 X
1	BOOT WHEATERSTRIP	\$	DSI/DS 178.20 50% ✓
1	BOOT REFLECTOR LAMP LH	\$	S ₂ 277.70 X
1	BOOT REFLECTOR LAMP RH	\$	CM 277.70 ✓
1	BOOT BADGE 'RENAULT'	\$	MC 82.40 ✓

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C**AAD2007-006**

1	BOOT BADGE	\$	<i>Ma</i>	95.80	✓
1	BOOT STRUT LH	\$	<i>Sn</i>	145.10	}
1	BOOT INNER TRIM BOARD	\$	<i>Sn</i>	611.00	
1	BOOT STRUT RH	\$	<i>Sn</i>	145.10	
1	BOOT HINGE LH	\$	<i>R</i>	254.20	
1	BOOT HINGE RH	\$	<i>R</i>	253.80	
1	BOOT LOCK	\$	<i>R</i>	246.60	
2	BOOT RUBBER PLUG	\$	<i>Sn</i>	139.30	}
1	EXHAUST REAR	\$	<i>R</i>	5,263.60	
1	EXHAUST CAP REAR	\$	<i>Sn</i>	125.40	}
1	REAR RH FENDER PANEL	\$	<i>R</i>	1,933.20	
1	WHEELARCH REAR RH	\$	<i>Sn</i>	275.40	}
1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Reform</i>	671.45	
1	TRUNK CARPET	\$	<i>Sn</i>	961.00	}
1	TRUNK CARPET EXTENSION	\$	<i>Sn</i>	412.80	
1	TRUNK CARPET SUPPORT	\$	<i>Sn</i>	409.80	
1	SPARE WHEEL PANEL	\$	<i>R</i>	1,229.40	
1	SPARE WHEEL PANEL TRIM	\$	<i>Sn</i>	612.21	
1	SPARE TYRE BOARD	\$	<i>Sn</i>	680.90	
1	SPARE WHEEL PANEL BRACKET RH	\$	<i>R</i>	70.60	
1	CHASSIS PANEL REAR RH	\$	<i>R</i>	2,192.40	
1	FENDER PANEL INNER REAR RH L70Y	\$	<i>R Sn</i>	1,241.60	
1	FENDER INNER BOARD RH L70Y	\$	<i>Sn</i>	561.40	
1	FENDER WHEEL HOUSING PANEL REAR RH	\$	<i>R</i>	4,682.09	}
1	KNUCKLE ARM REAR RH L70Y	\$	<i>Sn</i>	472.10	
1	LOWER ARM REAR RH L70Y	\$	<i>Sn</i>	543.50	
1	AXLE SPRING ARM RH	\$	<i>Sn</i>	220.60	
1	ABSORBER REAR RH	\$	<i>Sn</i>	217.30	
1	KNUCKLE HUB+ BEARING REAR RH	\$	<i>Sn</i>	272.30	
1	SUBFRAME ARM REAR RH	\$	<i>Sn</i>	198.33	
1	RODE- LONG REAR RH	\$	<i>Sn</i>	120.16	
1	REAR AXLE	\$	<i>Sn</i>	3,469.00	
TOTAL		\$		36,843.90	
10%		\$		3,684.39	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C**AAD2007-006****\$ 33,159.51****Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1SET BUMPER LOWER REAR RIVET
- 1SET BUMPER LOWER REAR CLIP
- 1 BOOT STICKER "Trans-cab"
- 1 BOOT STICKER "6555-3333"
- 1SET BOOT FINISHER CLIP
- 1 TAILLAMP CLIP LH
- 1 TAILLAMP CLIP RH
- 1 Rear Bumper Protector
- 1 REAR LICENCE PLATE WITH HOLDER
- 1 EXHAUST MOUNTING REAR
- 1 EXHAUST BRACKET REAR
- 1 FENDER INNER TRIM CLIP RH
- 1SET FENDER WHEELARCH REAR RH CLIP
- 2 REAR WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 REAR WINDSCREEN INNER SPONGE SEAL
- 2 SEAM SEALANT
- 1 REAR RENAULT TYRE
- 1 REAR RENAULT TYRE RIM
- 1 RENAULT TYRE RIM COVER
- 1 SPARE TYRE
- 1 SPARE TYRE RIM
- 1SET END PANEL TRIM CLIP
- 1SET END PANEL INSULATION PAD/ COVER

\$	Short	700.00	400.00
\$	na	75.00	✓
\$	na	40.00	X
\$	na	40.00	X
\$	na	45.00	X
\$	na	40.00	X
\$	na	45.00	X
\$	na	60.00	X
\$	na	75.00	✓
\$	na	80.00	30.00
\$	na	80.00	30.00
\$	na	40.00	X
\$	na	35.00	X
\$	na	35.00	5.00
\$	na	150.00	} X
\$	na	120.00	
\$	Sh	45.00	
\$	Sh	45.00	
\$	na	45.00	} X
\$	na	50.00	
\$	na	160.00	} X
\$	na	190.00	
\$	na	130.00	30.00
\$	na	180.00	} X
\$	na	330.00	
\$	na	380.00	
\$	na	65.00	
\$	Sh	330.00	} X
\$	Sh	380.00	
\$	na	45.00	} X
\$	na	200.00	

Trans-cab Auto Services Pte Ltd

AAD2007-006

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C

TOTAL \$ 4,235.00**TOTAL PARTS** \$ 37,394.51**LABOUR**

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	220.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>601</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>12001</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	<i>1201</i>
To repair and realign rear exhaust pipe.	\$	<i>Repaired</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>4</i> 170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD2007-006

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5980C

To Check Electrical Lighting Concerned.	\$	170.00	20%
To Rust-Proofing Of The Affected Areas.	\$	170.00	90%
To reinstall rear bumper parking sensor.	\$	170.00	60%
Putty and spray painting of the affected portion.	\$	6,000.00	1100%
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120%
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	↪ 380.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	↪ 380.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	↪ 380.00	X
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	↪ 380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	↪ 380.00	X

TOTAL \$ 17,390.00**Over All Total \$ 54,784.51****LUMP SUM (REPAIR DAY)**25 DAYS
8 days

LRA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: