

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40371

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0472/2020/NS
Date : 6-Jul-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SKT 442 Y**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Martina Chua Soo Hiang
Address : 30A Conway Drive
Singapore 558236
Telephone : (HP) +65 97371576
Type of Claim : Third Party Claims
Policy No. : 1700039953-02
Vehicle No : **SDS 7388 M**
Model Code : A4 Sedan 1.4 TFSI S
Model / Year : 14/8/2017
Engine No : CVN 040770
Chassis No : WAUZZZF42HA178460
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Jul-20
Place of Accident : Ang Mo Kio Central 2

Premium Automobiles

55 Ubi Road 1, Singapore 408419
Tel: 6396 1121 Fax: 6841 1121

Telefax

Estimated Labour Charges for Accident Vehicle. SDS 7388 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray rear bumper.	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDS 7388 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>Deformed</i>	\$ 2,079.00	✓
2	REAR BUMPER FIXING PARTS <i>Not in</i>	\$ 69.00	+
3	REAR BUMPER SECURING STRIP <i>Rec</i>	\$ 210.00	✓
4	REAR BUMPER SPOILER <i>Deformed</i>	\$ 234.00	✓
5	REAR LIGHT REFLECTOR - LH / RH <i>Rec</i>	2 \$ 78.00	✓
6	REAR BUMPER CARRIER <i>Not in</i>	\$ 845.00	✗
7	REAR BUMPER CARRIER SEAL <i>Not in</i>	2 \$ 26.00	✗
8	REAR BUMPER GUIDE SECTION - LH / RH <i>Rec</i>	2 \$ 42.00	+
9	REAR PARKING AID SENSOR - INNER / OUTER <i>Rec</i>	2 TBC	+
10	REAR PARKING AID SEAL RING <i>Not in</i>	4 \$ 14.00	✗
11	SUNDRIES <i>Not in</i>	\$ 200.00	✗
TOTAL SPARE PARTS CHARGES		: \$ 3,797.00	
TOTAL LABOUR CHARGES		: \$ 2,502.00	
GRAND TOTAL		: \$ 6,299.00	

All charges are not inclusive of GST.
Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Adrian L
08/07/20

Not Authorised 03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant