

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20007028/KRA3Q2
Date: 16/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070090857
Claimant Vehicle No :	SHC5728R	Insured Vehicle No :	GBD827L
Date of Loss:	03/07/2020	Nature of Claim:	TP
		Claim No:	7869477002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5728R		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002272
Reg. Date:	28/11/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC280378
Colour:	Metallic White/Red	Odometer:	671634 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,891.51	1,524.39	21,367.12	93.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,100.00	1,265.00	13,835.00	91.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,991.51	2,789.39	35,202.12	92.66
Approved Total (Overridden) (S\$)		2,250.00		

(S\$)	37,991.51	2,250.00	35,741.51	94.08
+ GST 7.00/7.00% (S\$)	2,659.41	157.50	2,501.91	94.08
Nett Amount (S\$)	40,650.92	2,407.50	38,243.42	94.08

INSPECTION

Date of Assignment: 06/07/2020

Date Inspected: 06/07/2020

Estimated Period of Repair: 2.5 days

Inspected At: Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
3	1		*BUMPER BRACKET FRT RH	Repair	186.50 FL	*- FL
4	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
5	1		*BUMPER RETAINER FRT RH	Distorted	101.40 FL	*101.40 FL
6	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
7	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
8	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
9	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
10	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
11	1		*HEADLAMP RH	Serviceable	743.60 FL	*- FL
12	1		*HEADLAMP PANEL FRT RH	Repair	128.30 FL	*- FL
13	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
14	1		*WHEELARCH FRT RH	Distorted	191.40 FL	*191.40 FL
15	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*- FL
16	1		*FENDER BRACKET FRT RH	Serviceable	106.40 FL	*- FL
17	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	*- FL
18	1		*FENDER BRACKET /GRILLE WING HOLDER	Serviceable	80.70 FL	*- FL
19	1		*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
20	1		*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
21	1		*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
22	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
23	1		*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*- FL
24	1		*BONNET	Repair	1,312.70 FL	*- FL
25	1		*BONNET STRUT RH	Serviceable	53.30 FL	*- FL
26	1		*BONNET HINGE RH	Repair	237.40 FL	*- FL
27	1		*LOWER ARM RH L70Y	Serviceable	192.70 FL	*- FL
28	1		*KNUCKLE ARM RH L70Y	Serviceable	481.50 FL	*- FL
29	1		*ABSORBER FRT RH L70Y	Serviceable	274.10 FL	*- FL
30	1		*DRIVESHAFT RH	Repair	1,355.70 FL	*- FL
31	1		*KNUCKLE HUB+BEARING RH	Not Necessary	272.30 FL	*- FL
32	1		*STABILIZER BAR FRT	Serviceable	427.90 FL	*- FL
33	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	*- FL
34	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
35	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
37	1		*WINDSCREEN FRONT	Serviceable	817.20 FL	*- FL
38	1		*RAIN SENSOR	Serviceable	296.90 FL	*- FL
39	1		*DOOR PANEL FRT RH	Repair	2,844.66 FL	*- FL
40	1		*DOOR HINGE UPPER FRT RH	Repair	274.50 FL	*- FL
41	1		*DOOR HINGE LOWER FRT RH	Repair	300.55 FL	*- FL
42	1		*DOOR CHECK FRT RH	Serviceable	194.77 FL	*- FL
43	1		*DOOR WEATHERSTRIP FRT RH	Serviceable	410.27 FL	*- FL
44	1		*DOOR MOULDING FRT RH	Serviceable	291.27 FL	*- FL
45	1		*DOOR SEAL FRT RH	Serviceable	72.82 FL	*- FL
46	1		*DOOR SEAL LOWER FRT RH	Serviceable	91.17 FL	*- FL
47	1		*DOOR MIRROR ASSY RH	Serviceable	1,483.40 FL	*- FL
48	1		*DOOR HARNESS WIRE RH	Serviceable	2,670.00 FL	*- FL
49	1		*BUMPER CLIP FRT	Necessary	75.00 FS	*75.00 FS
50	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	40.00 FS	*- FS
51	1		*BUMPER RETAINER CLIP FRT RH	Not Necessary	45.00 FS	*- FS
52	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	15.00 FS	*- FS
53	1		*BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
54	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
55	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	25.00 FS	*- FS
56	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
57	1		*WHEELARCH CLIP FRT RH	Necessary	45.00 FS	*45.00 FS
58	1		*FRONT RENAULT TYRE	Serviceable	300.00 FS	*- FS
59	1		*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
60	1		*FRON RENAULT TYRE RIM	Repair	380.00 FS	*- FS
61	1		*SET RADIATOR GRILLE SCREW	Not Necessary	35.00 FS	*- FS
62	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	55.00 FS	*- FS
63	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
64	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
65	1		*SET ROCKER PANEL CLIP	Not Necessary	45.00 FS	*- FS
66	1		*SET DOOR SEAL CLIP	Not Necessary	35.00 FS	*- FS
67	1		*WINDSCREEN MOULDING	Not Necessary	180.00 FS	*- FS
68	2		*FRONT WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
69	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	25,212.35	1,672.10
- List Item Discount on L Items 10.00/10.00% (\$)	2,320.84	147.71
Total Parts (\$)	22,891.51	1,524.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	6,000.00	500.00
2	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	660.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
5	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
10	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
11	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
12	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
13	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
14	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
15	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
Gross Labour Cost (\$\$)			15,100.00	1,265.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >