

Not Withheld
C/Smp &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5728R

AAD2007-012

06 JUL 2020

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC 5728R

VF1ABL15AUC280378

RENAULT

LATITUDE

3.7.2020

AIG

28-11-14

		LIST	
		PART	
1	BUMPER COVER FRT	\$	Bu 747.20 ✓
1	BUMPER SPOILER FRT	\$	Sn 344.70 X
1	BUMPER BRACKET FRT RH	\$	R 186.50 X
1	BUMPER ABSORBER FRT	\$	Sn 394.68 X
1	BUMPER RETAINER FRT RH	\$	Dir 101.40 ✓
1	BUMPER SUPPORT FRT	\$	Sn 10.70
1	BUMPER UNDERTRAY FRT	\$	Sn 292.50
1	BUMPER GRILLE LOWER FRT	\$	Sn 147.00 } X
1	BUMPER FOG LAMP GRILLE RH	\$	Sn 207.21
1	BUMPER BEAM FRT	\$	R 663.70
1	HEADLAMP RH	\$	Sn 743.60
1	HEADLAMP PANEL FRT RH	\$	R 128.30
1	FENDER PANEL FRT RH	\$	R 437.10 ✓
1	WHEELARCH FRT RH	\$	Dir 191.40 ✓
1	FENDER BRACKET LOWER RH	\$	Sn 11.80
1	FENDER BRACKET FRT RH	\$	Sn 106.40
1	FENDER INSULATOR RH	\$	Sn 66.30
1	FENDER BRACKET/ GRILL WING HOLDER	\$	Sn 80.70
1	RADIATOR GRILLE	\$	Sn 969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sn 225.36 } X
1	RADIATOR GRILLE FRAME	\$	Sn 686.00
1	FRAME FULL SUPPORT PANEL	\$	Sn 592.70
1	FRAME FULL SUPPORT BRACKET	\$	R 41.60
1	BONNET	\$	R 1,312.70
1	BONNET STRUT RH	\$	Sn 53.30
1	BONNET HINGE RH	\$	R 237.40

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5728R**AAD2007-012**

1	LOWER ARM RH L70Y	\$	192.70	}	X
1	KNUCKLE ARM RH L70Y	\$	481.50		
1	ABSORBER FRT RH L70Y	\$	274.10		
1	DRIVESHAFT RH	\$	1,355.70		
1	KNUCKLE HUB+BEARING RH	\$	272.30		
1	STABILIZER BAR FRT	\$	427.90		
1	WIPER RESERVOIR MOTOR	\$	82.60		
1	WIPER RESERVOIR	\$	179.60		
1	WIPER RESERVOIR NECK	\$	29.30		
1	ROCKER PANEL OUTER RH	\$	1,184.99		
1	WINDSCREEN FRONT	\$	817.20		
1	RAIN SENSOR	\$	296.90		
1	DOOR PANEL FRT RH	\$	2,844.66		
1	DOOR HINGE UPPER FRT RH	\$	274.50		
1	DOOR HINGE LOWER FRT RH	\$	300.55		
1	DOOR CHECK FRT RH	\$	194.77		
1	DOOR WEATHERSTRIP FRT RH	\$	410.27		
1	DOOR MOULDING FRT RH	\$	291.27		
1	DOOR SEAL FRT RH	\$	72.82		
1	DOOR SEAL LOWER FRT RH	\$	91.17		
1	DOOR MIRROR ASSY RH	\$	1,483.40		
1	DOOR HARNESS WIRE RH	\$	2,670.00		

TOTAL	\$	23,208.35
10%	\$	2,320.84
	\$	20,887.52

Special Nett

1	BUMPER CLIP FRT	\$	75.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	40.00	X
1	BUMPER RETAINER CLIP FRT RH	\$	45.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	15.00	X
1	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X

Trans-cab Auto Services Pte Ltd

AAD2007-012

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5728R

2	FRAME FULL SUPPORT PANEL NUT	\$	na	25.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1	WHEELARCH CLIP FRT RH	\$	na	45.00	✓
1	FRONT RENAULT TYRE	\$	na	300.00	X
1SET	Front licence plate with holder	\$	na	120.00	X
1	FRONT RENAULT TYRE RIM	\$	na	380.00	X
1SET	RADIATOR GRILLE SCREW	\$	na	35.00	X
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	55.00	X
1	Front Door Sticker "Trans-Cab"	\$	na	80.00	605na
1	Front Door Sticker "Classic"	\$	na	80.00	155na
1SET	ROCKER PANEL CLIP	\$	na	45.00	X
1SET	DOOR SEAL CLIP	\$	na	35.00	X
1	Windscreen moulding	\$	na	180.00	X
2	FRONT WINDSCREEN SEALANT	\$	na	150.00	X
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	130.00	X
TOTAL		\$		2,004.00	
TOTAL PARTS		\$		22,891.52	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 5001

To transfer of bonnet fittings, attachment and perform water seepage test.

\$ na 170.00 X

Putty and spray painting of the affected portion.

\$ 6,000.00 6601

To check steering geometry and computer wheel alignment

\$ 220.00 601

To transfer of front fender fittings, attachment and perform water seepage test.

\$ na 170.00 X

Trans-cab Auto Services Pte Ltd

AAD2007-012

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5728R

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	15/
To rust-proofing of the affected areas.	\$	170.00	6301
To check ABS and brake efficiency, final checking and testing.	\$	~ 380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	~ 170.00	X
TOTAL	\$	15,100.00	

Over All Total \$ 37,991.52**LUMP SUM (REPAIR DAY)****20 DAYS****2 1/2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Mutual agreement(s) is allowed
- All claims must be submitted to the insurer and is subject to approval from insurance Company

Acknowledged by Repairer

Signature:

Date: