

Not Authenical
L/Smp B

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

AAD2007-021

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

07 JUL 2020

SHD 18J

VF1ABL15AUC282698

RENAULT

LATITUDE

6.7.2020

FWD

10-06-16

PART		LIST	
1	ROCKER PANEL OUTER RH	\$	1,184.99 X
1	FENDER PANEL REAR RH	\$	1,933.20 X
1	WHEELARCH REAR RH	\$	275.40 X
1	DOOR PANEL REAR RH	\$	2,844.66 ✓
1	DOOR WEATHERSTRIP REAR RH	\$	311.60 X
1	DOOR REGULATOR REAR RH	\$	758.10 X
1	DOOR REGULATOR MOTOR REAR RH	\$	450.60 X
1	TAILLAMP RH	\$	401.40 X

TOTAL	\$	8,159.95
10%	\$	816.00
	\$	7,343.96

Special Nett

1SET	FENDER WHEELARCH REAR RH CLIP	\$	45.00	} X
2	REAR WINDSCREEN SEALANT	\$	150.00	
1	WINDSCREEN MOULDING	\$	190.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	120.00	
1	TAILLAMP CLIP RH	\$	35.00	
1	REAR RENAULT TYRE	\$	300.00	
1	REAR RENAULT TYRE RIM	\$	380.00	
1	RENAULT TYRE RIM COVER	\$	65.00	} X
1	Rear Bumper Protector	\$	120.00	
1	REAR DOOR STICKER "6555-3333"	\$	100.00	
1SET	ROCKER PANEL CLIP	\$	45.00 X	
TOTAL	\$	1,550.00		

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 18J

AAD2007-021

TOTAL PARTS \$ 8,893.96

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	2001
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	4 170.00	X
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	4 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To reinstall rear bumper parking sensor.	\$	4 170.00	X
Putty and spray painting of the affected portion.	\$	4,500.00	4001

To transfer of Rear Door fittings, attachment and perform water seepage test

- LKK Auto Consultants hereon certify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TOTAL \$ 10,570.00 601

Over All Total \$ 19,463.96

LUMP SUM (REPAIR DAY)

20-DAYS
 20days