

Trans-cab Auto Services Pte Ltd**AAD2007-021**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

Vehicle No.:	SHD 18J
Chassis No.:	VF1ABL15AUC282698
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	6.7.2020
Third Party Insurer :	FWD
Date of Registration:	10-06-16

	PART		LIST
1	ROCKER PANEL OUTER RH	\$	1,184.99
1	FENDER PANEL REAR RH	\$	1,933.20
1	WHEELARCH REAR RH	\$	275.40
1	DOOR PANEL REAR RH	\$	2,844.66
1	DOOR WEATHERSTRIP REAR RH	\$	311.60
1	DOOR REGULATOR REAR RH	\$	758.10
1	DOOR REGULATOR MOTOR REAR RH	\$	450.60
1	TAILLAMP RH	\$	401.40

TOTAL	\$	8,159.95
10%	\$	816.00
	\$	7,343.96

Special Nett

1SET	FENDER WHEELARCH REAR RH CLIP	\$	45.00
2	REAR WINDSCREEN SEALANT	\$	150.00
1	WINDSCREEN MOULDING	\$	190.00
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	120.00
1	TAILLAMP CLIP RH	\$	35.00
1	REAR RENAULT TYRE	\$	300.00
1	REAR RENAULT TYRE RIM	\$	380.00
1	RENAULT TYRE RIM COVER	\$	65.00
1	Rear Bumper Protector	\$	120.00
1	REAR DOOR STICKER "6555-3333"	\$	100.00
1SET	ROCKER PANEL CLIP	\$	45.00
TOTAL		\$	1,550.00

Trans-cab Auto Services Pte Ltd**AAD2007-021**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 18J

TOTAL PARTS	\$	8,893.96
--------------------	-----------	-----------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	170.00
To rust-proofing of the affected areas.	\$	170.00
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00
To transfer of tire, rim and on wheel balancing.	\$	170.00
To Check Electrical Lighting Concerned.	\$	170.00
To reinstall rear bumper parking sensor.	\$	170.00
Putty and spray painting of the affected portion.	\$	4,500.00
To transfer of Rear Door fittings, attachment and perform water seepage test.	\$	170.00
TOTAL	\$	10,570.00
Over All Total	\$	19,463.96

LUMP SUM (REPAIR DAY)**20 DAYS**