

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 13 Jul 2020

Preliminary Advice

Insured Vehicle No : SLK1295J
TP Vehicle No : SHC2375U Accident Date : 04/07/2020
Make : HYUNDAI IONIQ HYBRID Assignment Date : 07/07/2020
Date of Inspection : 07/07/2020 Est. Duration of Repair : 6 days
Inspection At : Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,205.31
Revised Amount	:S\$	15,098.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,098.24

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- The vehicle is economical for repair
- The vehicle is not economical for repair
- Part-by-Part repair
- Lump Sum repair

- The above survey was conducted on a 'without prejudice' basis.