

# 3A Automobile Pte Ltd

No 120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

## Estimate Report

Date: 23-Jun-2020

MS First Capital Insurance Ltd  
36 Robinson Road  
#16-01  
Singapore 068877  
Email: MotorClaims@msfirstcapital.com.sg  
Attn: Claims Officer  
Dept: Motor Claim Department

Vehicles Number: SLM 9412 A  
Make and Model: Mazda 3  
Date Of Accident: 16-Jun-2020

Tel: 65073848  
Fax: 65073849

Unit	List Items	Units Price	Prices
1	pc Rear Bumper <i>SCR</i>	\$ 1,129.00	\$ 1,129.00
S/Total			\$ 1,129.00
Less 20%			(\$225.80)
			\$ 903.20

1	pc Reverse Sensor		\$ 200.00
			\$ 1,103.20

### Labour Charges

To Remove & Replace the Damaged Parts as Listed Above, including Reinstallments of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts.

\$ ~~200~~ 300.00

To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint On All Affected Areas with Oven Spray Booth Facilities.

\$ ~~200~~ 350.00

Total \$ 1,753.20

Yours faithfully.

3A Automobile Pte Ltd  
Person to contact: Alwin / Lydia  
Mobilephone : 9786 8677 / 6738 7777

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

903.20  
400.00  
1303.20

20%  
1042.56

4/5 - 1050.00  
2 days

Rasul  
Hp 90010068

2 days  
4/5

08/07/2020  
P 11/10

Resurvey after repair