

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G

SHD219X - AIG

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

Not Authorised
\$ 2632.98
Repair B4 paint

AAD1705-020**SHD219X - ROEL**

VF1ABL15AUC281661
 RENAULT
 LATITUDE
 02.05.2017
AIG

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>Ru</i> 968.78	✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 303.60	X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 703.14	X
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 139.81	X
5	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 159.40	X
6	1	BUMPER RETAINER FRT LH	\$	<i>D</i> 116.47	✓
7	1	BUMPER SUPPORT FRT LH(headlamp lower)	\$	<i>Sn</i> 18.37	X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 363.71	} <i>X</i>
9	1	AIR CLEANER LOWER	\$	<i>Sn</i> 271.26	
10	1	AIR CLEANER HOSE	\$	<i>Sn</i> 58.57	
11	1	STEERING PUMP ELECTRIC	\$	<i>Sn</i> 1,543.08	
12	1	BONNET	\$	<i>R</i> 1,493.56	
13	1	RADAITOR GRILLE	\$	<i>Sn</i> 1,313.68	
14	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>ru</i> 173.36	
15	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i> 1,041.35	
16	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 473.77	
17	1	HEADLALMP RH	\$	<i>Sn</i> 911.10	
18	1	HEADLALMP LH	\$	<i>Sn</i> 911.10	
19	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 134.59	} ✓
20	1	FENDER PANEL FRT LH	\$	<i>R</i> 602.95	
21	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95	X
22	1	FENDER WHEELARCH FRT LH (Linner)	\$	<i>D</i> 107.33	✓
23	1	DOOR MIRROR LH	\$	<i>Sn</i> 1,141.08	X
24	1	DOOR FRT LH	\$	<i>R</i> 2,188.20	X
25	1	DOOR SEAL FRT LH	\$	<i>Sn</i> 52.83	X
26	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 759.61	X

TOTAL	\$	16,553.64
10%	\$	1,655.36
	\$	14,898.28

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD219X - AIG**Specical Nett**

1	1SET	FRONT BUMPER CLIP	\$	<i>nn</i> 66.00 ✓
2	1SET	WHEELARCH CLIP LH	\$	<i>nn</i> 66.00 ✓
3	1	TOW COVER FRT	\$	<i>sn</i> 14.50 X
4	1	CAP HUB LH FRT	\$	<i>sn</i> 35.00 X
5	1	RIM LH FRT	\$	<i>sn</i> 385.00 X
6	1	TYRE LH FRT	\$	<i>sn</i> 330.00 X
7	1	DOOR SEAL CLIP FRT LH	\$	<i>nn</i> 4.68 X
8	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 X
9	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 X
10	1SET	BUMPER SUPPORT FRT CLIP LH	\$	<i>nn</i> 9.80 X
11	1SET	BUMEPR RETAINER FRT CLIP LH	\$	<i>nn</i> 12.50 X

TOTAL	\$	1,033.48
TOTAL PARTS	\$	15,931.76

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$

4,200.00

400

To Check Electrical Lighting Concerned.

\$

170.00

150

Putty and spray painting of the affected portion.

\$

4,500.00

440

To check steering geometry and computer wheel alignment

\$

nn 220.00 X

Towing Fees

\$

nn 120.00 X

To transfer of tire, rim and on wheel balancing.

\$

nn 170.00 X

To remove and renew power steering pump, oil cooler pipe and final checking and testing.

\$

nn 440.00 X

To rust-proofing of the affected areas.

\$

170.00

300

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD219X - AIG**AAD1705-020**

To transfer of door fittings, attachment and
perform water seepage test.

\$

~170.00 X

TOTAL	\$	10,160.00
Over All Total	\$	26,091.76

(PARTS BY PARTS) Repair Days~~15 Days~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: