

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40530

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0478/2020/NS
Date	:	7-Jul-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLF 6857 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Wang Yili
Address	:	28A Jalan Lempeng #03-15 Singapore 128808
Telephone	:	(HP) +65 90175685
Type of Claim	:	Third Party Claims
Policy No.	:	2100507480-03
Vehicle No	:	SLN 587 H
Model Code	:	A4 Sedan 1.4 TFSI S
Model / Year	:	20/4/2017
Engine No	:	CVN 033179
Chassis No	:	WAUZZZF45HA126031
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	6-Jul-20
Place of Accident	:	28A Jalan Lempeng 128808

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLN 587 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rhs headlight control units and power modules. To carry out calibration.	S/N \$ 350.00	
2	To dismantle and reinstall rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 350.00	
3	To dismantle and renew front bumper and rhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00	
4	To respray front bumper and rhs front fender and rhs front door.	\$ 3,000.00	
5	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,992.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 587 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,010.00	
2	FRONT BUMPER FIXING PARTS	\$ 269.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 67.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 185.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 198.00	
6	FRONT BUMPER AIR GUIDE - RH	\$ 59.00	
7	RADIATOR GRILLE	\$ 1,084.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 127.00	
9	FRONT BUMPER CARRIER	\$ 757.00	
10	FRONT BUMPER GUIDE SECTION - RH	\$ 36.00	
11	FRONT BUMPER COVER	\$ 120.00	
12	FRONT BUMPER FOAM FILLER PIECE	\$ 117.00	
13	LOCK CARRIER BRACKET	\$ 129.00	
14	LOCK CARRIER BRACKET SUPPORT - LH / RH	2 \$ 54.00	
15	CAUTION SIGN STICKER	NEC \$ 13.00	
16	AIRCON STICKER	NEC \$ 7.00	
17	HORN - RH LOW TONE	\$ 119.00	
18	SPRING SHACKLE - RH	\$ 27.00	
19	FRONT FENDER - RH	\$ 722.00	
20	FRONT FENDER ATTACHMENT PARTS	\$ 190.00	
SUB TOTAL SPARE PARTS		: \$ 6,290.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 587 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER CLOSING ELEMENT - RH	\$ 47.00	
22	FRONT FENDER BRACKET - RH FRONT	\$ 33.00	
23	DEFORMATION ELEMENT BRACKET - RH REAR	\$ 46.00	
24	FRONT FENDER BRACKET - RH FRONT	\$ 30.00	
25	FRONT FENDER BRACE - RH	\$ 112.00	
26	WHEEL HOUSING LINER - RH	\$ 228.00	
27	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 86.00	
28	WHEEL SPOILER	\$ 69.00	
29	WHEEL SPOILER TRIM	\$ 34.00	
30	STONE CHIP GUARD	\$ 48.00	
31	FENDER LEDGE COVER - UPPER	\$ 29.00	
32	FENDER LEDGE COVER - LOWER	\$ 21.00	
33	LED HEADLIGHT - RH	\$ 7,321.00	
34	LIFT CYLINDER - RH	\$ 198.00	
35	LIFT CYLINDER CORRUGATED PIPE	\$ 88.00	
36	TEMPERATURE SENSOR BRACKET	\$ 18.00	
37	RADIATOR AIR GUIDE - RH	\$ 27.00	
38	RADIATOR AIR GUIDE - RH	\$ 12.00	
39	FRONT NO PLATE	S/N \$ 60.00	
40	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 15,097.00	
TOTAL LABOUR CHARGES		: \$ 5,992.00	
GRAND TOTAL		: \$ 21,089.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant