

Ag Asia-4S

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305409527
 REGN NO : SHC7243J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 11.08.2016
 DATE/TIME IN : 07.07.2020 08:25
 ACCIDENT DATE : 06.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-0579-G	REAR BUMPER	1	1,106.00 20.00 884.80 <i>de</i>
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00 20.00 182.40 <i>Cur</i>
0003	04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00 20.00 17.60 <i>nei</i>
0004	04-01-0103-0787-G	BOOTLID EMBLEM-I40	1	27.90 20.00 22.32 <i>x</i>
0005	04-01-0103-0786-G	BOOTLID EMBLEM-CRDI	1	27.90 20.00 22.32 <i>x</i>
0006	09-01-9999-0068-A	REVERSE SENSOR	1	135.70 2.00 135.70 <i>nei</i>

SUB-TOTAL : 1,265.14

JOB NATURE

0000	20-05	Rear Bumper Adv.Sticker	50.00	<i>nei</i>
0001	PB	PANEL BEATING	300.00	<i>280</i>
0002	SP	SPRAYPAINT CHARGE	500.00	<i>300</i>
0003	L	R/I REVERSE SENSOR	120.00	<i>30</i>

SUB-TOTAL : 970.00

Tanpin 17495744
 WP
 7/7/20 @ 3pm
 Lm psm
 Resurvey after repair
 02 days
 Tanpin e lth auto. wv.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 07.07.2020

Time: 11:21:49

Page: 2

Ag B19

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305409527

REGN NO : SHC7243J

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : I-40

DATE OF REGN : 11.08.2016

DATE/TIME IN : 07.07.2020 08:25

ACCIDENT DATE : 06.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,235.14

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

COMFORTDELGRO ENGINEERING

Member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 572701

Mainline - 65 6383 8230 Facsimile - 65 6280 9755

Workshops

55 Luyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 501296

220 Hougang Avenue 4 Singapore 530249

24 Serangoon Loop Singapore 758156

7 Sungei Kadut Way Singapore 128191

501 Mishun Industrial Park A Singapore 758131

Date/Time: 07.07.2020 11:10

Page : 1

m: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO.: 305409527

ER
CITYCAB PTE LTD
7010070
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188

REGN NO: SHC7243J	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 07.07.2020 08:25
YR OF MANU. 11.08.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU092625	COMPLETION DATE/TIME:

ST CARD NO


JOB DESCRIPTION

ident Date: 06.07.2020

URE: 3P 06.07.2020

TO LABOR CODE

DESCRIPTION



& PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Vehicle No.

Exit Pass

SHC7243J

LIMITS

Vehicle No.

SHC7243J