

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20007069/DGS3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00010922-01

Claimant
Vehicle No : FBQ3013E **Insured Vehicle No :** SDY8200H

Date of Loss: 17/06/2020 Nature of Claim: TP Claim No: 1202000018533

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ3013E		
Make & Model:	YAMAHA GDR155A (AEROX), 155cc	Engine No:	G3J8E0104623
Reg. Date:	02/09/2019 (Man. Year: 2019)	Chassis No:	MH3SG4640KJ055807
Colour:	Red	Odometer:	0 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/80 R14	Rear Tyre Size:	140/70 R14
Front Left Side:	Pirelli 3 mm	Rear Left Side:	Pirelli 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,641.00	3,074.50	1,566.50	33.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	790.00	380.00	410.00	51.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,431.00	3,454.50	1,976.50	36.39
Approved Total (Overridden) (\$\$)		2,750.00		
Nett Amount (\$\$)	5,431.00	2,750.00	2,681.00	49.36
+ Loss of Use (4.0 x S\$20.00/day) (\$\$)		80.00		
+ Other Costs (\$\$)		40.00		
Nett Liability (\$\$)		2,870.00		

INSPECTION

Date of Assignment: 07/07/2020

Date Inspected: 08/07/2020 Inspected At:

S9 Motor Trading Pte Ltd (HQ)
4001 ANG MO KIO INDUSTRIAL
PARK 1 #01-21
Singapore 569622

Estimated Period of Repair: 4.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Sep 2020)	
Parts:	N/A	YAMAHA GDR155A (AEROX) 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBQ3013E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET MIRROR	O/S Cut	120.00 FL	*60.00 FL
2	2		*FRONT PANEL -SIDE LH/RH	Cut	380.00 FL	*380.00 FL
3	1		*CENTRE PANEL	Not Necessary	120.00 FL	*- FL
4	1		*FRONT MUDGUARD	Not Necessary	150.00 FL	*- FL
5	1		*SET FORK TUBE	Distorted	480.00 FL	*480.00 FL
6	1		*FORK UNDERBRACKET	Damaged	190.00 FL	*190.00 FL
7	1		*HANDLE BAR	Distorted	135.00 FL	*135.00 FL
8	1		*BRAKE LEVER O/S	Cut	95.00 FL	*95.00 FL
9	2		*BELLY PAN-L/RH	Not Necessary	380.00 FL	*- FL
10	1		*RH STEP BOARD	Bent	180.00 FL	*180.00 FL
11	1		*LH CENTRE PANEL	Cut	200.00 FL	*200.00 FL
12	1		*LH FOOTREST -REAR	Cut	190.00 FL	*190.00 FL
13	1		*SIDE STAND	Not Necessary	180.00 FL	*- FL
14	1		*REAR LH GARNISH COVER	Cut / Broken	190.00 FL	*190.00 FL
15	1		*TRANSMISSION COVER-TOP	Cut	210.00 FL	*210.00 FL
16	1		*TRANSMISSION COVER-LOWER	Cut	180.00 FL	*180.00 FL
17	1		*REAR FOOTREST BRACKET	Bent	120.00 FL	*120.00 FL
18	1		*MAIN STAND	Not Necessary	180.00 FL	*- FL
19	1		*SET BALANCER	O/S Cut	190.00 FL	*95.00 FL
20	1		*SET BODY DECAL STICKER	Repeated	220.00 FL	*- FL
21	1		*EXHAUST GUARD	Cut	280.00 FL	*280.00 FL
22	1		*AIR INTAKE COVER	Mtg Broken	120.00 FL	*120.00 FL
23	1		*REAR BOX	Cut	450.00 FS	*180.00 FS
24	1		*BODY DECAL STICKER	Necessary	150.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,090.00	3,385.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	449.00	310.50
Total Parts (\$\$)	4,641.00	3,074.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	40.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS ,ALIGN & ETC	New	350.00	180.00
3	REMOVE & REPLACE FORK TUBE ,BRACKET, TOP UP FORK OIL	New	150.00	80.00
4	PUTTY & RESPRAY -TOUCH PAINT WORK	New	250.00	120.00
Gross Labour Cost (\$\$)			790.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >