

Date: 03.07.2020
 Vehicle No: SML2665B
 Model: TOYOTA VOXY HYBRID 1.8V
 Chassis: ZWR800350488-2018
 Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: GBH7720T
 Date of Accident: 03.07.2020

*Not Authorized
 Missing 34 paint 7 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	<i>Ref</i>	\$861.70 ✓
2	REAR BUMPER CLIPS	10	\$5.80	<i>m</i> \$58.00 ✓
3	REAR BUMPER SIDE BRACKET LH	1		\$75.30 ?
4	REAR TAIL LAMP LOWER GARNISH COVER LH	1		<i>R</i> \$196.50 X
5	REAR TAIL LAMP LOWER GARNISH COVER BRACKET LH	1		<i>IL</i> \$170.20 X
6	REAR FENDER QUARTER PANEL LH	1	<i>R</i>	\$1,595.40 ✓
7	REAR SLIDING DOOR LH	1	<i>R</i>	\$1,817.60 ✓
8	REAR SLIDING DOOR INNER TRIM CLIPS LH	12	\$5.50	\$17.50 ?
SUB TOTAL				\$4,792.20
LESS 25%				-\$1,198.05
PARTS TOTAL				\$3,594.15

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR SIDE GLASS SEALANT LH	1	<i>Ref</i>	\$80.00 <i>4000</i>
S/N TOTAL				\$80.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS & ETC.

7501
 \$1,200.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR TAIL LAMP GARNISH COVER LH, REAR FENDER QUARTER PANEL LH, REAR SLIDING DOOR LH, FUEL FILLER LID PANEL & ETC.

8001
 \$1,000.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR SLIDING DOOR LH INNER MECHANISM & ETC. TO REFFECT REPLACE OF REAR SLIDING DOOR LH.

601
 \$120.00

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR. TO EFFECT REPLACE OF REAR BUMPER.

501
 \$80.00

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

201
 \$60.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 03.07.2020
Vehicle No: SML2665B
Model: TOYOTA VOXY HYBRID 1.8V
Chassis: ZWR800350488-2018
Reg.Year: 2019

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GBH7720T
Date of Accident: 03.07.2020

LABOUR CHARGES TO REMOVE & REFIX, REPLACE REAR QUARTER PANEL SIDE GLASS
LH, SIDE GLASS SEALANT LH & ETC. TO EFFECT REPLACE OF REAR QUARTER PANEL LH.

Pol
\$120.00

LABOUR CHARGES TO REMOVE & REFIX FUEL FILLER PIPE & ETC. TO EFFECT REPLACE
OF REAR QUARTER PANEL LH.

601
\$80.00

LABOUR TOTAL \$2,660.00

TingAn

TOTAL \$6,334.15

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223