

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jul 2020 Edit Reg		07 Jul 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: EDMUND ONG TEONG LIAT , ID: S7487603Z									
Main Claimant: SBS TRANSIT LTD , Co. Reg. No.: 199206653MPTE01									
Vehicle Reg. No.: SBS6223K		Date of Loss: 02/07/2020 07:00 - :59 [366 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6736517617SG		Policy/Cover Note No.: 2100465995 (Comprehensive) Coverage: 16/05/2020 - 15/05/2021							
Vehicle Reg. No. (Insured): SLC4542T		Policy No. (Claimant):							
		Excess:							
Repairer: Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4, 489946 Bedok - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/07/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
AIG_SG (08/07/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SBS6223K (6736517617SG)**
[SLC4542T]
TP
SBS TRANSIT LTD
Jul 2 2020 7:00AM
[EDMUND ONG TEONG LIAT]
Sbs Transit Ltd (Bedok)

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	02/09/20 12:06	Chassis Number													Load JPG	☒				
2	02/09/20 12:06	Odometer Reading													Load JPG	☒				
3	02/09/20 12:06	General View													Load JPG	☒				
4	02/09/20 12:06	General View													Load JPG	☒				
5	02/09/20 12:06	General View													Load JPG	☒				
6	02/09/20 12:06	General View													Load JPG	☒				
7	02/09/20 12:06	General View													Load JPG	☒				
8	02/09/20 12:06	General View													Load JPG	☒				
9	02/09/20 12:06	General View													Load JPG	☒				
10	02/09/20 12:06	General View													Load JPG	☒				
11	02/09/20 12:06	General View													Load JPG	☒				
12	02/09/20 12:06	General View													Load JPG	☒				
13	02/09/20 12:06	General View													Load JPG	☒				
14	02/09/20 12:06	General View													Load JPG	☒				
15	02/09/20 12:06	General View													Load JPG	☒				
16	02/09/20 12:06	General View													Load JPG	☒				
17	02/09/20 12:06	General View													Load JPG	☒				
18	02/09/20 12:06	General View													Load JPG	☒				
19	02/09/20 12:06	General View													Load JPG	☒				
20	02/09/20 12:06	General View													Load JPG	☒				
21	02/09/20 12:06	General View													Load JPG	☒				
22	02/09/20 12:06	General View													Load JPG	☒				
23	02/09/20 12:08	Replacement Part Photo													Load JPG	☒				
24	02/09/20 12:08	Replacement Part Photo													Load JPG	☒				
25	02/09/20 12:08	Replacement Part Photo													Load JPG	☒				
26	02/09/20 12:08	After Repair Photo													Load JPG	☒				
27	02/09/20 12:08	After Repair Photo													Load JPG	☒				
28	02/09/20 12:08	After Repair Photo													Load JPG	☒				
29	02/09/20 12:08	After Repair Photo													Load JPG	☒				
Documentation															1 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print				
1	07/07/20 16:11	ACKNOWLEDGEMENT EMAIL TO AIG DD07072020													Load PDF					
2	07/07/20 16:11	EMAIL FROM AIG DD07072020													Load PDF					
3	09/07/20 10:10	TP GIA REPORT													Load PDF					
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print				
1	08/07/20 17:52	OI GIA REPORT													Load PDF					

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20007074/T1ES3S2**Date:** 08/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100465995
Claimant Vehicle No :	SBS6223K	Insured Vehicle No :	SLC4542T
Date of Loss:	02/07/2020	Nature of Claim:	TP
		Claim No:	6736517617SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6223K	Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ 0405G, 12.0 D (A)	Chassis No:	WEB62808323123394
Reg. Date:	01/01/1990 (Man. Year: 1990)	Odometer:	482112 km
Colour:	Multi-colour		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	07/07/2020		
Date Inspected:	08/07/2020	Inspected At:	Sbs Transit Ltd (Bedok) (HQ) 1470 BEDOK NORTH AVE 4 Singapore 489946
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH CORNER BUMPER	Repair	0.00 F	*- F
2	1		*REAR LH CORNER BUMPER REFLECTOR	Cut	0.00 F	*- F
3	1		*REAR LH SIDE COMPARTMENT DOOR	Bent	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >