




Liberty Insurance
Member of Liberty Mutual Group

Liberty Insurance Pte Ltd
11 MAY 2017



75
Liberty Insurance Pte Ltd
51 Club Street #03-00
Liberty House
Singapore 069428
Tel: (65) 6221 8611
Fax: (65) 6224 1047

AUTOMOBILE INSPECTION REPORT (IN-HOUSE SURVEY)

*Proceed to offer

Type of Survey:	Type of claim and Assignment:		Type of Report:	Claim No
Physical	OD	Re-Survey	Finalized	AVS17/0994 (CMPO)
Vehicle Inspected:	SLH5820H		Date of Accident:	12/04/2017
Insured Vehicle:			Date of Inspection:	21/04/2017
Survey held at:	HUI YANG MOTOR PTE LTD. SIN MING AUTOCAR E#04-02		Attd. by:	WORKSHOP PERSONNEL

2. Vehicle Particulars & Condition (static test only)

Make & Model:	TOYOTA VELLFIRE 2.4 (A)		Year:	24/8/2012
Excess / Loading:	TBA		Colour:	BLACK
Brakes:	In order / NA	Steering:	In order / NA	
Modifications:				

3. Adjustment of cost of repairs

Adjusted: →

Item	Unit*	\$/Unit	Amount
Panel Beat.			1850
Spray Paint.			2000
Mechanic			750
Others*			400
Parts	See attached list		26750.02
Total (PBP)	-	-	\$ 31,750.02

W/Shop estimation:

\$37,096.02

~~23979.7~~

Lump Sum: \$22,000

? Items:

Estimated repair period: 14 Working days.

Authorised Repairs: YES

(This inspection is conducted on a "Without Prejudice Basis")

* Units: Days - Hours - Panels (Labour + Mat) *Others: Aircon gas - Wheel align. - Electronic diagnostic -

Tow - Glasses - Head-light align. - ...

4. Remarks

Market value : SGD 120,000.00 Supplementary expected : YES

LTA Rebate : SGD 89,129.00

Economical repair value : SGD 30,871.00 Recommended for repair: YES

* WORKSHOP REQUEST FOR LUMP SUM REPAIR \$22,000.00 WITH NO FURTHER SUPPLEMENTARY *

Description of Damages: FRONT AND REAR PORTION

Damages Consistent: Yes

Inspection conducted by: Kaharudin Bin Abdul Karim

Date & Signature: 8/5/2017 *Kaharudin*

