



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2101389

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/03/2021
Reference CC6/CTI20007080/Des3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 6423G
Insured Veh. SFM 5151A
Claim No. SNM20D202316
Policy No. DMPCSNA00007532001
Accident Date 01/07/2020
Inspection Date 02/07/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20007080/Des3q2 Date: 08/03/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFM 5151A	Veh. Inspected	SH 6423G	
Policy No.	DMPCSNAA00007532001	Coverage (\$)	0.00	
Claim No.	SNM20D202316	Excess (\$)	0.00	
Assign From		Assign Date	02/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHC851CVJU102918	Colour	BLUE	
Odometer	277008 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/07/2020	Inspection Date	02/07/2020	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6423G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	DENTED	2,480.40	2,480.40
1	BOOT LID RUBBER	NECESSARY	187.40	187.40
1	BOOT LID LOCK UPPER	DAMAGED	224.00	224.00
1	BOOT LID "H" EMBLEM	NECESSARY	28.00	28.00
1	EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	BOOT LID LAMP (LH)	CRACKED	794.40	794.40
1	BOOT LID TRIMBOARD	NOT NECESSARY	259.70	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOT LID TRIMBOARD,CENTRE	NOT NECESSARY	159.60	-
1	BOOT LID TRIMBOARD SIDE (LH)	NOT NECESSARY	92.50	-
1	BOOT LID TRIMBOARD REAR	NOT NECESSARY	124.80	-
2	REAR WINDSCREEN MOULDING @\$142.30	NECESSARY	284.60	284.60
1	REAR BUMPER	TORN	459.40	459.40
1	REAR BUMPER REINFORCEMENT	DENTED	394.80	394.80
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @ \$188.10	NOT NECESSARY	376.20	-
1	ANTENNA ASSY-SMARTK	MOUNTING BROKEN	689.50	689.50
1	REAR BUMPER CENTRE MOULDING ASSY	TORN	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	BENT	47.50	47.50
1	REAR BUMPER STAY	NOT NECESSARY	138.10	-
2	REAR BUMPER SIDE RETAINER (LH/RH) @\$85.80	NOT NECESSARY	171.60	-
1	REAR BUMPER COVER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE	DISLODGE	123.85	123.85
2	REAR BUMPER SIDE UNDER (LH/RH) @\$123.10	N/S BROKEN / O/S NOT NECESSARY	246.20	123.10
1	REAR BUMPER REAR HOOK	NOT NECESSARY	94.60	-
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$82.90	N/S DISLODGE / O/S NOT NECESSARY	165.80	82.90
1	REAR BUMPER TOWING COVER	CUT / DISTORTED	98.80	98.80

Report Ref No. CC6/CTI20007080/Des3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	SOCKET BROKEN	328.60	328.60
2	LICENCE LAMP (LH/RH) @\$85.30	NOT NECESSARY	170.60	-
1	LICENCE LAMP WIRE	NOT NECESSARY	135.80	-
1	TAIL LAMP (LH)	MOUNTING CRACKED	870.40	870.40
1	TAIL LAMP QUARTER PANEL (LH)	NOT NECESSARY	208.90	-
1	REAR PANEL	DENTED	532.00	532.00
1	ANTENNA ASSY-TRUNK	NOT NECESSARY	689.50	-
1	REAR PANEL GARNISH	DEFORMED / BROKEN	346.80	346.80
1	SPARE TYRE HOLDER	NOT NECESSARY	223.10	-
1	SPARE WHEEL LOCK NUT	NOT NECESSARY	89.50	-
1	SPARE TYRE PANEL	DENTED	892.50	892.50
1	PANEL ASSY-REAR FLOOR SIDE (LH)	NOT NECESSARY	39.40	-
1	REAR FLOOR CHASSIS MEMBER (LH)	NOT NECESSARY	1,863.40	-
1	REAR TRAY TOOLS BOX LH	BENT / DEFORMED	693.20	693.20
1	REAR TRAY LUGGS CENTER	MOUNTING BROKEN	354.20	354.20
1	EXHAUST PIPE INSULATOR	NOT NECESSARY	235.00	-
1	EXHAUST SILENCER	NOT NECESSARY	943.50	-
1	EXHAUST PIPE HANGER	NOT NECESSARY	29.20	-
1	ASSY BSD BLIND SPOT RADAR (LH)	BENT	1,625.00	1,625.00
1	WIRING HARNESS BWS EXT	NOT NECESSARY	988.90	-
1	REAR FENDER (LH)(ADDITIONAL)	DENTED	1,768.30	1,768.30
	LESS 20% DISCOUNT		-4,241.88	-2,791.70
			16,967.52	11,166.80
	SPECIAL NETT ITEMS			
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	35.00	35.00
1	BOOT LID COMFORT CABLINK TEL NO STICKER (SN)	NOT NECESSARY	30.00	-
1	REAR NO PLATE + TRIM COVER (SN)	CRACKED	45.00	45.00
2	REAR WINDSCREEN SEALANT @\$46.00 (SN)	NECESSARY	92.00	92.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	180.00	180.00
			382.00	352.00

Report Ref No. CC6/CTI20007080/Des3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		1,400.00	900.00
	SPRAY PAINTING CHARGE.		1,200.00	700.00
	WIRING CHARGE.		120.00	30.00
	TUFF KOTE.		120.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX REAR WINDSCREEN GLASS.		240.00	120.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE/REFIX UNDERCARRIAGE (RR).	NOT NECESSARY	400.00	-
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE/REFIX FUEL TANK.	NOT NECESSARY	80.00	-
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	80.00	-
	FOUR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			4,910.00	1,980.00
	GRAND TOTAL		22,259.52	13,498.80
RECOMMENDED COST OF REPAIRS				13,498.80

Report Ref No. CC6/CTI20007080/Des3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 6423G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 6423G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 6423G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

