

ASS. REC. BY:

006/C11 200070801 Res3

ASSIGNMENT

OE July 2026

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 7/P % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH 6423G Yr Regn: 2018 JulyType: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /Truck / Trailer or 1580Make: Hyundai Ioniq C.C. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 277008 T/Radio: Insured / Std / NI / NAEng/No: G4LEJU043220C/No: KMHC851CVJU102918Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 195/65 R 15R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WestlakeFront S mm Rear S mmR/Bal. S mmL/Bal. S mmD.O.A. 01/07/2020 D.O.I. 02/07/2020Survey held at Bifrost Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Chm Taping SFM 5151A

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S+RS, SI

Photos

Others

TOTAL

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 1-Jul-20

INSURANCE: China Taiping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH6423G

Description	Qty	List Price	Amount	
Boot Lid <i>Demol</i>	1	\$ 2,480.40	\$ 2,480.40	✓
Boot Lid Rubber <i>Hec</i>	1	\$ 187.40	\$ 187.40	✓
Boot Lid Lock Upper <i>Demol</i>	1	\$ 224.00	\$ 224.00	✓
Boot Lid 'H' Emblem <i>Hec</i>	1	\$ 28.00	\$ 28.00	✓
Emblem-Hybrid <i>Hec</i>	1	\$ 24.30	\$ 24.30	✓
Emblem-Ioniq <i>Hec</i>	1	\$ 31.30	\$ 31.30	✓
Boot Lid Lamp(LH) <i>Crack</i>	1	\$ 794.40	\$ 794.40	✓
Boot Lid Trimboard <i>NH</i>	1	\$ 259.70	\$ 259.70	X
Boot Lid Trimboard Clips (10pcs) <i>NH</i>	1	\$ 11.00	\$ 11.00	X
Boot Lid Trimboard, Centre <i>NH</i>	1	\$ 159.60	\$ 159.60	X
Boot Lid Trimboard SIDE (LH) <i>NH</i>	1	\$ 92.50	\$ 92.50	X
Boot Lid Trimboard REAR <i>NH</i>	1	\$ 124.80	\$ 124.80	X
Rear Windscreen moulding <i>Hec</i>	2	\$ 142.30	\$ 284.60	✓
Rear Bumper <i>Turn</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Reinforcement <i>Demol</i>	1	\$ 394.80	\$ 394.80	✓
Rear Bumper Reinforcement Bracket (LH/RH) <i>Crack</i>	2	\$ 188.10	\$ 376.20	✓
Antenna Assy-SMARTK <i>broken mounting</i> <i>photo</i>	1	\$ 689.50	\$ 689.50	✓
Rear Bumper Centre Moulding Assy <i>Turn</i>	1	\$ 451.25	\$ 451.25	✓
Rear Bumper Lower Centre Moulding Assy <i>St</i>	1	\$ 47.50	\$ 47.50	✓
Rear Bumper Stay <i>NH</i>	1	\$ 138.10	\$ 138.10	X
Rear Bumper Side retainer (LH/RH) <i>NH</i>	2	\$ 85.80	\$ 171.60	X
Rear Bumper Cover Clips <i>Hec</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Under Centre <i>distorted</i>	1	\$ 123.85	\$ 123.85	✓
Rear Bumper Side Under(LH/RH) <i>N/S broken o/s NH</i>	2	\$ 123.10	\$ 246.20	✓
Rear Bumper Rear Hook <i>NH</i>	1	\$ 94.60	\$ 94.60	X
Rear Bumper Reflector Lamp(LH/RH) <i>N/S distorted o/s NH</i>	2	\$ 82.90	\$ 165.80	✓
Rear Bumper Towing Cover <i>cut / distorted</i>	1	\$ 98.80	\$ 98.80	✓
Rear Bumper Reserve Light (Parking Brake Light) <i>Seal broken</i>	1	\$ 328.60	\$ 328.60	✓
Licence Lamp (LH/RH) <i>NH</i> <i>photo</i>	2	\$ 85.30	\$ 170.60	X
Licence Lamp WIRE <i>NH</i>	1	\$ 135.80	\$ 135.80	X
Tail Lamp(LH) <i>mounting crack</i>	1	\$ 870.40	\$ 870.40	✓
Tail Lamp Quarter Panel(LH) <i>NH</i>	1	\$ 208.90	\$ 208.90	X
Rear Panel <i>Demol</i>	1	\$ 532.00	\$ 532.00	✓
Antenna Assy - TRUNK <i>NH</i>	1	\$ 689.50	\$ 689.50	X
Rear Panel Garnish <i>distorted / broken</i>	1	\$ 346.80	\$ 346.80	✓
Spare Tyre Holder <i>NH</i>	1	\$ 223.10	\$ 223.10	X
Spare Wheel Lock Nut <i>NH</i>	1	\$ 89.50	\$ 89.50	X
Spare Tyre Panel <i>Demol</i>	1	\$ 892.50	\$ 892.50	✓
Panel Assy-Rear Floor Side (LH) <i>NH</i>	1	\$ 39.40	\$ 39.40	X
Rear Floor Chassis Member (LH) <i>NH</i>	1	\$ 1,863.40	\$ 1,863.40	X
Rear tray tools box LH <i>St / distorted</i>	1	\$ 693.20	\$ 693.20	✓
REAR TRAY LUGGS CENTER <i>mainly broken</i>	1	\$ 354.20	\$ 354.20	✓

Exhaust Pipe Insulator <i>NH</i>		1	\$ 235.00	\$ 235.00	X
Exhaust Silencer <i>NH</i>		1	\$ 943.50	\$ 943.50	X
Exhaust Pipe Hanger <i>NH</i>		1	\$ 29.20	\$ 29.20	X
Assy BSD Blind Spot Radar (LH) <i>NH ST</i>		1	\$ 1,625.00	\$ 1,625.00	X
Wiring Harness BWS Ext <i>NH</i>		1	\$ 988.90	\$ 988.90	X
SUB TOTAL				\$ 19,441.10	
LESS 20%				\$ 3,888.22	
DISCOUNTED TOTAL				\$ 15,552.88	
Boot Lid Comfort Logo & Tel No. Sticker <i>NH</i>	SN	1	\$ 35.00	\$ 35.00	✓
Boot Lid Comfort Cablink Tel No. Sticker <i>NH</i>	SN	1	\$ 30.00	\$ 30.00	X
Rear No. Plate + Trim Cover <i>Coke</i>	SN	1	\$ 45.00	\$ 45.00	✓
Rear Windscreen Sealant <i>NH</i>	SN	2	\$ 46.00	\$ 92.00	✓
Rear Bumper Reverse Sensor <i>Don</i>	SN	1	\$ 180.00	\$ 180.00	✓
SUB TOTAL				\$ 382.00	
Labour Charge					
Panel Beating		1	\$1,400.00	\$1,400.00	900/-
Spray Painting Charge		1	\$1,200.00	\$1,200.00	700/-
Wiring Charge		1	\$120.00	\$120.00	30/-
Tuff Kote		1	\$120.00	\$120.00	40/-
Towing Charge		1	\$80.00	\$80.00	40/-
Remove/Refix Rear Windscreen Glass		2	\$120.00	\$240.00	120/-
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	40/-
Remove/Refix Undercarriage (RR)		1	\$400.00	\$400.00	40/-
Re-set Rear ABS System		1	\$400.00	\$400.00	40/-
Remove/Refix Fuel Tank		1	\$80.00	\$80.00	40/-
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	40/-
Four Wheel Alignment		1	\$120.00	\$120.00	40/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	150/-
TOTAL LABOUR				\$4,910.00	
ESTIMATE TOTAL				\$ 20,844.88	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

02/07/2020 @ 1730hrs

Not Another
Part by Part.

6 days

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 3-Jul-20

INSURANCE: Chua Teiping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH6423G (S)

Description	Qty	List Price	Amount
Rear Fender(LH) <i>Denture</i>	1	\$ 1,768.30	\$ 1,768.30
SUB TOTAL			\$ 1,768.30
LESS 20%			\$ 353.66
DISCOUNTED TOTAL			\$ 1,414.64

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1 year

LKK Auto

[Signature]