

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 1-Jul-20

INSURANCE: China Triping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH6423G

Description	Qty	List Price	Amount
Boot Lid <i>Demol</i>	1	\$ 2,480.40	\$ 2,480.40
Boot Lid Rubber <i>Hec</i>	1	\$ 187.40	\$ 187.40
Boot Lid Lock Upper <i>Demol</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>Hec</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>Hec</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>Hec</i>	1	\$ 31.30	\$ 31.30
Boot Lid Lamp(LH) <i>Crack</i>	1	\$ 794.40	\$ 794.40
Boot Lid Trimboard <i>NH</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>NH</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>NH</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH) <i>NH</i>	1	\$ 92.50	\$ 92.50
Boot Lid Trimboard REAR <i>NH</i>	1	\$ 124.80	\$ 124.80
Rear Windscreen moulding <i>Hec</i>	2	\$ 142.30	\$ 284.60
Rear Bumper <i>Turn</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>Demol</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>Crack</i>	2	\$ 188.10	\$ 376.20
Antenna Assy-SMARTK <i>broken mounting</i> <i>photo</i>	1	\$ 689.50	\$ 689.50
Rear Bumper Centre Moulding Assy <i>Turn</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>St</i>	1	\$ 47.50	\$ 47.50
Rear Bumper Stay <i>NH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH/RH) <i>NH</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Cover Clips <i>Hec</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>distorted</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH/RH) <i>N/S broken o/s NH</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Rear Hook <i>NH</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Reflector Lamp(LH/RH) <i>N/S distorted o/s NH</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Towing Cover <i>cut / distorted</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>Socket broken</i>	1	\$ 328.60	\$ 328.60
Licence Lamp (LH/RH) <i>NH</i> <i>photo</i>	2	\$ 85.30	\$ 170.60
Licence Lamp WIRE <i>NH</i>	1	\$ 135.80	\$ 135.80
Tail Lamp(LH) <i>mounting crack</i>	1	\$ 870.40	\$ 870.40
Tail Lamp Quarter Panel(LH) <i>NH</i>	1	\$ 208.90	\$ 208.90
Rear Panel <i>Demol</i>	1	\$ 532.00	\$ 532.00
Antenna Assy - TRUNK <i>NH</i>	1	\$ 689.50	\$ 689.50
Rear Panel Garnish <i>distorted / broken</i>	1	\$ 346.80	\$ 346.80
Spare Tyre Holder <i>NH</i>	1	\$ 223.10	\$ 223.10
Spare Wheel Lock Nut <i>NH</i>	1	\$ 89.50	\$ 89.50
Spare Tyre Panel <i>Demol</i>	1	\$ 892.50	\$ 892.50
Panel Assy-Rear Floor Side (LH) <i>NH</i>	1	\$ 39.40	\$ 39.40
Rear Floor Chassis Member (LH) <i>NH</i>	1	\$ 1,863.40	\$ 1,863.40
Rear tray tools box LH <i>St / distorted</i>	1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>mainly broken</i>	1	\$ 354.20	\$ 354.20

Exhaust Pipe Insulator <i>NH</i>		1	\$ 235.00	\$ 235.00	X
Exhaust Silencer <i>NH</i>		1	\$ 943.50	\$ 943.50	X
Exhaust Pipe Hanger <i>NH</i>		1	\$ 29.20	\$ 29.20	X
Assy BSD Blind Spot Radar (LH) <i>Ht St</i>		1	\$ 1,625.00	\$ 1,625.00	X✓
Wiring Harness BWS Ext <i>NH</i>		1	\$ 988.90	\$ 988.90	X
SUB TOTAL				\$ 19,441.10	
LESS 20%				\$ 3,888.22	
DISCOUNTED TOTAL				\$ 15,552.88	
Boot Lid Comfort Logo & Tel No. Sticker <i>Hec</i>	SN	1	\$ 35.00	\$ 35.00	✓
Boot Lid Comfort Cablink Tel No. Sticker <i>NH</i>	SN	1	\$ 30.00	\$ 30.00	X
Rear No.Plates + Trim Cover <i>Cikuk</i>	SN	1	\$ 45.00	\$ 45.00	✓
Rear Windscreen Sealant <i>Hec</i>	SN	2	\$ 46.00	\$ 92.00	✓
Rear Bumper Reverse Sensor <i>D-m</i>	SN	1	\$ 180.00	\$ 180.00	✓
SUB TOTAL				\$ 382.00	
Labour Charge					
Panel Beating		1	\$1,400.00	\$1,400.00	900/
Spray Painting Charge		1	\$1,200.00	\$1,200.00	700/
Wiring Charge		1	\$120.00	\$120.00	30/
Tuff Kote		1	\$120.00	\$120.00	40/
Towing Charge		1	\$80.00	\$80.00	40/
Remove/Refix Rear Windscreen Glass		2	\$120.00	\$240.00	120/
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	40/
Remove/Refix Undercarriage (RR)		1	\$400.00	\$400.00	40/
Re-set Rear ABS System		1	\$400.00	\$400.00	40/
Remove/Refix Fuel Tank		1	\$80.00	\$80.00	40/
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	40/
Four Wheel Alignment		1	\$120.00	\$120.00	20/
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	150/
TOTAL LABOUR				\$4,910.00	
ESTIMATE TOTAL				\$ 20,844.88	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

02/07/2020 @ 1730hrs

Not Antenna
Part by Part.

6 days

[Signature]

LKK Auto

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 3-Jul-20

INSURANCE: China Taiping

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH6423G (S)

Description	Qty	List Price	Amount
Rear Fender(LH) <i>Dent</i>	1	\$ 1,768.30	\$ 1,768.30
SUB TOTAL			\$ 1,768.30
LESS 20%			\$ 353.66
DISCOUNTED TOTAL			\$ 1,414.64

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1 year

LKK Auto

[Signature]