



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

06/07/2020

Accident date: 04/07/2020

Estimated repair cost for vehicle no: SLL1943S MAZDA 2 1.5i 17'

CHASSIS: JM6DJ2HAA01100868

S/n	Qty	Items / Nett	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$968.10	✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$115.50	\$231.00	+
3	2	Rear Boot Lid Shock Absorber <i>new</i>	\$130.80	\$261.60	+
4	1	Rear Boot Lid Emblem		\$58.20	✓
5	1	Rear Boot Lid Mazda 2 Logo <i>new</i>		\$57.90	✓
6	1	Rear Boot Lid Skyactive Logo		\$67.60	✓
7	1	Rear Boot Lid Number Plate <i>cont. dent.</i>		\$50.00	✓
8	2	Rear Boot Lid Number Plate Lamp <i>cracked</i>	\$74.70	\$149.40	✓
9	2	Rear Boot Lid Side Reflector <i>new</i>	\$238.20	\$476.40	+
10	1	Rear Boot Lid Lock <i>Damaged</i>		\$196.90	✓
11	1	Rear Boot Lid Weatherstrip <i>at</i>		\$112.90	✓
12	1	Rear Boot Lid Trim Board <i>3 Not</i>		\$302.60	+
13	8	Rear Boot Lid Trim Board Clip <i>new</i>	\$6.50	\$52.00	+
14	2	Rear Taillamp <i>cracked</i>	\$395.30	\$790.60	✓
15	4	Rear Taillamp Clip <i>new</i>	\$8.00	\$32.00 20	
16	2	Rear Taillamp Panel <i>3 Not</i>	\$287.70	\$575.40	+
17	2	Rear Taillamp Lower Panel <i>3 Not</i>	\$324.60	\$649.20	+
18	1	Rear Bumper <i>Dented</i>		\$954.50 851	
19	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30	
20	2	Rear Bumper Side Retainer <i>new</i>	\$22.80	\$45.60	✓
21	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00 424/sw	
22	1	Rear End Panel <i>Dented</i>		\$656.00	✓
23	1	Rear End Panel Top Garnish <i>Dented</i>		\$96.60	✓
24	2	Rear Fender <i>new</i>	\$948.00	\$1,896.00	+
25	2	Rear Fender Cowling	\$173.00	\$346.00	+
26	12	Rear Fender Cowling Clip <i>3 Not</i>	\$6.50	\$78.00	+
27	2	Rear Fender Inner Trimboard <i>new</i>	\$426.30	\$852.60	+
28	16	Rear Fender Inner Trimboard Clip	\$6.50	\$104.00	+
29	1	Rear Spare Tyre Top Cover <i>Dented</i>		\$303.90	✓

30	1	Rear Spare Tyre Panel Foam Tool Box	crushed -	\$235.80	✓
31	1	Rear Exhaust	Rep's	\$940.20	x
32	2	Rear Exhaust Mounting	Not m	\$27.10	\$54.20 x

4690.50

Subtotal :- \$12,040.20

3757.40

S.N: 220.

Labour charges

To remove & refit cushion & trim board

~~\$280.00~~ 80

To remove & refit reverse sensor

~~\$100.00~~ 60

To remove & refit rear windscreen

~~\$120.00~~ ✓

Gum

\$50.00 ✓

To remove & refit rear exhaust

~~\$280.00~~ 80.

To check wiring

~~\$100.00~~ 30

Tuff kote

2480

~~\$150.00~~ 80

Towing

~~\$150.00~~ x

Panel beating

~~\$1,400.00~~ 1000

Spray painting

~~\$1,400.00~~ 900

To transfer boot lid fittings.

180
80.

Subtotal :- \$4,030.00

16,620.20

Total:- \$16,670.20

Supplementary: 296

total: 6748.40

4/s S.H.K.

06 Days

S.H.K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

06/07/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 04/07/2020

Supplementary cost for vehicle no: SLL1943S MAZDA 2 1.5l 17'

CHASSIS: JM6DJ2HAA01100868

S/n	Qty	Items	U/price	Amount
1	2	Rear Bumper Bracket <i>Damaged</i>	\$45.00	\$90.00 ✓
2	1	Rear Spare Tyre Lower Cover <i>torn</i>		\$280.00 ✓

Total:- \$370.00

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

370

296