

Denise Tay (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Wednesday, 8 July 2020 2:57 PM
To: Denise Tay (LKKAuto)
Subject: Re: Paper Survey GX3476G (audit check)

Hi Denise,

Audit check done for GX3476G, found no net value been work out. I already spoken to Sun Pin.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Wednesday, 8 July 2020 1:03 PM
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: FW: Paper Survey GX3476G (audit check)

Hi simon,

Previously PRS is Mr MA survey photo can be view in merimen. Paper survey done by sun pin

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6271-0351 | email: sur@lkkauto.com | fax: 6271-8802

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Sent: Wednesday, 8 July 2020 12:10 PM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: Paper Survey GX3476G

Hi Denise,

Please refer attachment.

Final amount \$4,750. Repair day 4 days. (L/S, before gst).

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)