



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2006299
INV Date 14/09/2020
Reference CC6/CTI20007082/Kda3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SKD 8681E
Insured Veh. SLM 9408M
Claim No. SNM20D202364
Policy No. DMHCSNA00000391900
Accident Date 03/07/2020
Inspection Date 06/07/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20007082/Kda3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 14-09-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 9408M	Veh. Inspected	SKD 8681E
Policy No.	DMHCSNA00000391900	Coverage (\$)	0.00
Claim No.	SNM20D202364	Excess (\$)	0.00
Assign From		Assign Date	06/07/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JTDGG20W005002537	Colour	METALLIC GREY
Odometer	142120	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	7 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/07/2020	Inspection Date	06/07/2020
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 8681E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BENT	1,175.00	1,175.00
2	TAILGATE REFLECTOR @ \$277.60	N/S CUT / O/S SERVICEABLE	555.20	277.60
1	TAILGATE HANDLE - CHROME	SERVICEABLE	252.10	-
1	TAILGATE - TOYOTA LOGO	NECESSARY	70.24	70.24
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	361.60	-
1	TAILLAMP N/S	CRACKED	301.60	301.60
1	REAR BUMPER	BENT / CRACKED	491.90	491.90
1	REAR BUMPER RETAINER - BELOW TAILLAMP	DISTORTED	40.40	40.40
1	REAR BUMPER RETAINER - SIDE	DISTORTED	92.30	92.30
1	END PANEL	BENT	453.90	453.90
1	END PANEL TOP GARNISH	SERVICEABLE	253.10	-
	LESS 25% DISCOUNT		-1,011.84	-725.73
			3,035.50	2,177.21
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	SCRATCHED	220.00	200.00
			220.00	200.00
	<u>LABOUR</u>			
	TO REMOVE / TRANSFER REAR WINDSCREEN GLASS TO NEW DOOR.		180.00	120.00
	TO TRANSFER TAILGATE DOORBOARD ALL ATTACHMENTS TO NEW DOOR.		100.00	60.00
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS. REPAIR / RESHAPE DAMAGED / DENTED AREAS. REPLACE / ALIGN ALL PARTS INTO POSITION. INCLUISVE OF THE REPAIR OF TAILGATE LOCK.		950.00	600.00
	TO SPRAY PAINT.		750.00	600.00
			1,980.00	1,380.00
	GRAND TOTAL		5,235.50	3,757.21
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CC6/CTI20007082/Kda3s2



Report Ref No. CC6/CTI20007082/Kda3s2

A handwritten signature in black ink, consisting of the letters 'KSC' in a stylized, cursive script.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.