

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

Not Authorize
11 Sep 8?
Money After Paint
5 days

06, JULY 2020

China Taiping Insurance (S) PL
105 Cecil Street
#18-00
The Octagon S 63896138

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SLM9408M
Accident involving vehicle no: SKD8681E/SLM9408M
DOA: 03/07/2020 AT Along PIE twds CTE

Dear officer incharge:
Estimate cost of repair for vehicle no: SKD8681E
To supply—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Description	Qty	Amount
Tailgate	1 <i>27</i>	1,175.00 ✓
Tailgate reflector @277.6 <i>NIS</i>	1 <i>61 9/1 2</i>	277.60 <i>27</i>
Tailgate handle-chrome	1	<i>52</i> 252.10 X
Tailgate -TOYOTA logo	1	<i>70</i> 70.24 ✓
Tailgate lock	1	<i>36</i> 361.60 X
Taillamp <i>NIS</i>	1 <i>CM</i>	301.60 ✓
Rear bumper	1 <i>471 CM</i>	491.90 ✓
Rear bumper retainer-below taillamp	1	<i>40</i> 40.40 ✓
Rear bumper retainer-side	1	<i>92</i> 92.30 ✓
End panel	1	<i>45</i> 453.90 ✓
End panel top garnish	1	<i>25</i> 253.10 X
Parts		3,769.74
Parts less 25%		942.44
		2,827.31

Reverse sensor
To remove/transfer rear windscreen glass to new door
To transfer tailgate doorboard and all attachments to new door
To remove damaged parts and attachments
Repair/reshape damaged/dented areas
Replace/align all parts into position
To spray paint

Sur 220.00 *2000*
180.00 *1201*
100.00 *601*

950.00 *6001*
750.00 *6001*

5,027.31

5,235.50#