

Not Authorised
C/Smp &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9800T

AAD2007-022

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

07 JUL 2020

SHB 9800T

VF1ABL15AUC273246

RENAULT

LATITUDE

5.7.2020

FCIL

31/7/2013

		LIST		
		<i>Bul/Ret</i>		
	PART			
1	BUMPER COVER REAR	\$	561.70	✓
1	BUMPER LOWER REAR	\$	411.90	✓
1	BUMPER BRACKET CTR REAR	\$	98.10	} X
1	BUMPER BRACKET SIDE RH REAR	\$	82.10	
1	BUMPER RETAINER RH REAR	\$	59.80	
1	BUMPER REFLECTOR RH	\$	16.60	
1	BUMPER BRACKET SIDE LH REAR	\$	80.80	
1	BUMPER RETAINER LH REAR	\$	54.20	
1	BUMPER REFLECTOR LH	\$	16.60	
1	BUMPER BEAM REAR	\$	547.80	
1	BUMPER BEAM BRACKET LH REAR	\$	114.50	
1	BUMPER BEAM BRACKET RH REAR	\$	100.90	
1	BOOT REAR	\$	1,677.20	
1	BOOT FINISHER	\$	344.70	
1	BOOT WHEATERSTRIP	\$	178.20	
1	BOOT REFLECTOR LAMP LH	\$	277.70	
1	BOOT REFLECTOR LAMP RH	\$	277.70	
1	BOOT BADGE 'RENAULT'	\$	82.40	} X
1	BOOT BADGE	\$	95.80	
1	TAILLAMP RH	\$	401.40	
1	TAILLAMP LH	\$	401.40	
1	OUTER PANEL REAR (End Panel)	\$	745.80	
1	OUTER PANEL REAR (End Panel) TRIM	\$	404.56	
1	EXHAUST CAP REAR	\$	125.40	
TOTAL		\$	7,157.26	
10%		\$	715.73	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9800T**AAD2007-022**\$ 6,441.53**Special Nett**

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	75.00	✓
1SET BUMPER BRACKET CTR CLIP	\$	40.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	40.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	45.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	40.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	45.00	X
1SET BUMPER LOWER REAR RIVET	\$	65.00	X
1SET BUMPER LOWER REAR CLIP	\$	75.00	✓
1SET BOOT FINISHER CLIP	\$	40.00	}
1 BOOT STICKER "Trans-cab"	\$	80.00	
1 BOOT STICKER "6555-3333"	\$	80.00	
1 TAILLAMP CLIP RH	\$	35.00	
1 TAILLAMP CLIP LH	\$	35.00	
1 Rear Bumper Protector	\$	130.00	}
1SET Rear licence plate with holder	\$	110.00	
TOTAL	\$	1,635.00	

TOTAL PARTS \$ 8,076.53**LABOUR**

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2007-022

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9800T

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	200L
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	220L
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	50L
To Check Electrical Lighting Concerned.	\$	4 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
TOTAL	\$	14,330.00	

Over All Total \$ 22,406.53

(LUMP SUM) Repair Days

20 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: