

Not Authorized
Resurvey B6 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7928Y

AAD2007-018

01207-45

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 7928Y

JTDKB3FU003081806

TOYOTA

PRIUS

4.7.2020

AIG

27-06-19

07 JUL 2020

PART

- 1 RIGHT SIDE VIEW MIRROR

LIST

	\$	cm	1,436.60	✓
TOTAL	\$		1,436.60	
25%	\$		359.15	
	\$		1,077.45	

Special Nett

- 1 FRONT DOOR STICKER 'TRANS-CAB'

	\$	nn	100.00	X
TOTAL	\$		100.00	

TOTAL PARTS \$ **1,177.45**

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 3,000.00 501

To Rust-Proofing Of The Affected Areas.

\$ nn 170.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 601

To Check Electrical Lighting Concerned.

\$ 170.00 201

TOTAL \$ **6,340.00**

Over All Total \$ **7,517.45**

(PART-BY-PART) Repair Days

~~10~~ days

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: