

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>  
Sent: Wednesday, 8 July 2020 3:14 pm  
To: SUR <sur@lkkauto.com>  
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Lim, Kok-Chong <Kok-Chong.Lim@aig.com>  
Subject: SME8293M/ OD / 30773443535G

Hi,

- 2 To remove and transfer the headlight control units and power modules. To carry out calibration. S/N 5 400.00

Since when do Audi have this labour? And why it is given when 0.5 day labour is given for replacement?

Thanks & Regards

Victor Koh  
AIG  
Claims Technical Controller  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120  
Tel +65 6419 1785 | Fax +65 68357416  
Victor-ck.koh@aig.com | [www.aig.com](http://www.aig.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Have just clarified with Premium Automobile.  
The additional new labour charges is for the removal of headlamps @ \$250 per piece.

And therefore, in the main labour charges, the removal fee for headlamps should be excluded.  
We will do the necessary adjustments.