

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40144

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0467/2020/NS
Date : 3-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Rasul

3 days - ok - jb - 16 Aug 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : ERBE Singapore Pte Ltd
Address : 25 International Business Park
#02-55/56
Singapore 609916
Telephone : +(HP) 97537561
Type of Claim : Own Damage Claim
Policy No. : 1800120277-01
Vehicle No : **SME 8293 M**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Oct-18
Engine No : DAX 041384
Chassis No : WAUZZZF2J2197223
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Jul-20
Place of Accident : CTE (AMK Ave 3/5 Exit)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 8293 M

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$	280.00	\$ 280.00
2	To remove and transfer lhs headlight control units and power modules. To carry out calibration.	S/N \$	400.00	nn
3	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$	1,200.00	\$ 500.00
4	To respray front bumper, front bumper lower spoiler and both front wheel arch trims.	\$	3,000.00	\$ 1,500.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,072.00	\$ 2,472.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8293 M

S/N Parts Description		Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER	\$ 2,473.00	\$ 1,978.40
2	FRONT BUMPER FIXING PARTS	\$ 254.00	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$ 212.00	
4	FRONT BUMPER GRILLE - CENTRE	\$ 135.00	
5	FRONT SPOILER	\$ 717.00	\$ 573.20
6	FRONT BUMPER UNDERRUN BAR	\$ 452.00	\$ 361.60
7	FRONT BUMPER CLOSING ELEMENT	\$ 163.00	\$ 130.40
8	RADIATOR GRILLE	\$ 3,327.00	\$ 2,661.60
9	QUATTRO INSCRIPTION	\$ 90.00	\$ 71.76
10	STRIKER PLATE	\$ 230.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$ 1,090.00	\$ 436.00
12	FRONT BUMPER END CAP - LH / RH	2 \$ 174.00	
13	LOCKING CLIP	4 \$ 15.00	
14	FRONT BUMPER CARRIER	\$ 868.00	
15	FRONT BUMPER FOAM FILLER PIECE	\$ 272.00	\$ 217.20
16	FOAM FILLER PIECE COVER	\$ 121.00	
17	CAUTION SIGN STICKER	NEC \$ 13.00	
18	AIRCON STICKER	NEC \$ 18.00	
19	FRONT PARKING AID SENSOR - INNER / OUTER	2 TBC	
20	FRONT PARKING AID SEAL RING	4 \$ 14.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 10,638.00	\$ 6,430.16

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8293 M

S/N Parts Description		Damage Parts & Prices		
		S/Nett	Remarks	
	C/F		\$	6,430.16
21	FRONT WHEEL COVER - LH / RH	2 \$ 1,190.00	\$	952.00
22	RADIATOR AIR GUIDE - LH / RH	2 \$ 110.00		
23	RADIATOR AIR GUIDE - CENTRE	\$ 40.00		
24	RADIATOR AIR GUIDE - LOWER	\$ 45.00		
25	HEADLIGHT MOUNTING - LH	\$ 112.00	\$	89.20
26	LED HEADLIGHT - LH	\$ 7,555.00		
27	LIFT CYLINDER - LH / RH	2 \$ 264.00		
28	FRONT NO PLATE	S/N \$ 60.00	\$	60.00
29	ADDED PARTS - SEE ATTACHED	\$ 270.00	\$	216.00
30	SUNDRIES	\$ 300.00		
TOTAL SPARE PARTS CHARGES		: \$ 20,584.00	\$	7,747.36
TOTAL LABOUR CHARGES		: \$ 5,072.00	\$	2,472.00
GRAND TOTAL		: \$ 25,656.00	\$	10,219.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699

Supplementary Estimate 1

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No		PA/OD/0467/2020/NS 20-Jul-20 Glory Tan 1 OF 1 SME 8293 M Audi Q5 2.0 TFSI qu	
Quantity	Description	Unit Price	Amount		
<u>Parts</u>					
1	Wheel spoiler RHS	\$ 153.00	\$ 122.40		
2	Headlight mounting RHS	\$ 117.00	\$ 93.60		
TOTAL		\$ 270.00	\$ 216.00		

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant