

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40144

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0467/2020/NS
Date : 3-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : ERBE Singapore Pte Ltd
Address : 25 International Business Park
#02-55/56
Singapore 609916
Telephone : +(HP) 97537561
Type of Claim : Own Damage Claim
Policy No. : 1800120277-01
Vehicle No : **SME 8293 M**
Model Code : Audi Q5 2.0 TFSI qu
Model / Year : Oct-18
Engine No : DAX 041384
Chassis No : WAUZZZF2J2197223
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Jul-20
Place of Accident : CTE (AMK Ave 3/5 Exit)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 8293 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00 /	
2	To remove and transfer lhs headlight control units and power modules. To carry out calibration.	S/N \$ 400.00 /	
3	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00 500	
4	To respray front bumper, front bumper lower spoiler and both front wheel arch trims.	\$ 3,000.00 950 + 550 = 1500	
5	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 5,072.00	

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0467/2020/NS 20-Jul-20 Glory Tan 1 OF 1 SME 8293 M Audi Q5 2.0 TFSI qu
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Wheel spoiler RHS <i>cm</i>	\$ 153.00	
2	Headlight mounting RHS <i>cm</i>	\$ 117.00	
TOTAL		\$ 270.00	

For Premium Automobiles Pte Ltd

P. Lim
21/07/2020

Authorised Signature

*Subject to
insurance approval*

Car-in

20/7/2020.

LQ / Long . AIG R&S

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

wip: 40144

3 bays

Material List for Accident Vehicle Regn No. SME 8293 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>de</i>	\$	2,473.00
2	FRONT BUMPER FIXING PARTS ?	\$	254.00
3	FRONT BUMPER CLOSING ELEMENT - LH / RH ?	2 \$	212.00
4	FRONT BUMPER GRILLE - CENTRE X	\$	135.00
5	FRONT SPOILER <i>cut</i>	\$	717.00
6	FRONT BUMPER UNDERRUN BAR <i>cut</i>	\$	452.00
7	FRONT BUMPER CLOSING ELEMENT <i>de</i>	\$	163.00
8	RADIATOR GRILLE <i>cut</i>	\$	3,327.00
9	QUATTRO INSCRIPTION <i>new</i>	\$	90.00
10	STRIKER PLATE ?	\$	230.00
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>cut</i>	21 \$	1,090.00
12	FRONT BUMPER END CAP - LH / RH X	2 \$	174.00
13	LOCKING CLIP X	4 \$	15.00
14	FRONT BUMPER CARRIER ?	\$	868.00
15	FRONT BUMPER FOAM FILLER PIECE <i>cut</i>	\$	272.00
16	FOAM FILLER PIECE COVER ?	\$	121.00
17	CAUTION SIGN STICKER X	NEC \$	13.00
18	AIRCON STICKER X	NEC \$	18.00
19	FRONT PARKING AID SENSOR - INNER / OUTER X	2	TBC
20	FRONT PARKING AID SEAL RING <i>new</i>	4 \$	14.00
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 10,638.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8293 M

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	FRONT WHEEL COVER - LH / RH <i>free</i> ✓	2	\$ 1,190.00	
22	RADIATOR AIR GUIDE - LH / RH X	2	\$ 110.00	
23	RADIATOR AIR GUIDE - CENTRE X		\$ 40.00	
24	RADIATOR AIR GUIDE - LOWER X		\$ 45.00	
25	HEADLIGHT MOUNTING - LH <i>? free</i> ✓		\$ 112.00	
26	LED HEADLIGHT - LH ?		\$ 7,555.00	
27	LIFT CYLINDER - LH / RH X	2	\$ 264.00	
28	FRONT NO PLATE <i>bt</i> ✓	S/N	\$ 60.00	
29	SUNDRIES ?		\$ 300.00	
TOTAL SPARE PARTS CHARGES		:	\$20,314.00	
TOTAL LABOUR CHARGES		:	\$ 5,072.00	
GRAND TOTAL		:	<u>\$25,386.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Headlight mounting RH
wheel spoiler RHS