

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG: 200707743D GST REG: 200707743D

6-Jul-20

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6994 G

1 pc	Boot lid	\$	1,119.00 <i>bt</i>
1 pc	Boot lid lock	\$	99.00 <i>bt</i>
1 pc	Bootlid lock cable	\$	35.00 <i>x</i>
1 pc	Bootlid striker	\$	21.00 <i>Ry</i>
1 pc	Bootlid emblem	\$	27.00 <i>ner</i>
1 pc	Bootlid CRDi	\$	29.00 <i>ner</i>
1 pc	Boot lid rubber weatherstrip	\$	96.00 <i>py</i>
1 pc	Boot lid lower garnish	\$	290.00 <i>am</i>
2 pcs	Bootlid hinges @ \$66.00	\$	132.00 <i>Ry</i>
1 pc	End panel	\$	250.00 <i>bt</i>
1 pc	End panel inner garnish	\$	74.00 <i>de</i>
1 pc	Rear bumper	\$	696.00 <i>de</i>
1 pc	Rear bumper lower cover	\$	206.00 <i>de</i>
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 <i>ner</i>
1 pc	Rear bumper inner sponge	\$	114.00 <i>ner</i>
1 pc	Rear bumper reinforcement	\$	607.00 <i>bt</i>
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 <i>?</i>
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 <i>?</i>
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 <i>?</i>
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00 <i>x</i>
2 pcs	n/s & o/s tail lamp @ \$421.00	<i>o/s-?</i> \$	842.00 <i>n/s am</i>
2 pcs	n/s & o/s reflector @ \$350.00	\$	700.00 <i>x</i>
		\$	5,667.00
Less 10%		\$	566.70
		\$	5,100.30

### S/NETT

1 set	Rear bumper clips		
1 set	End panel inner garnish clips	\$	48.00 <i>3 One</i>
1 set	Bootlid inner trim clips	\$	30.00 <i>2 One</i>
1 set	Bootlid lower garnish clips	\$	52.00 <i>2 One</i>
1 set	Bootlid stickers	\$	60.00 <i>2 One</i>
1 set	Reverse sensor	\$	100.00 <i>ner</i>
		\$	280.00 <i>200</i>
			<i>na</i>

6-Jul-20

**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6994 G**

Sundry	\$ 50.00 <sup>20</sup>
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 <sup>30</sup>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <sup>60</sup>
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the the same	\$ 950.00 <sup>600</sup>
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel.	\$ 800.00 <sup>600</sup>
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 <sup>30</sup>
	<u>\$ 7,920.30</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Taufik 97495744  
WP'  
8/7/20 @ 4pm  
humpun 04 days  
Resurvey after repair  
taufik @ 11 auto.wm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: