

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

6-Jul-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6994 G

1 pc	Boot lid	\$	1,119.00	bt ✓
1 pc	Boot lid lock	\$	99.00	bt ✓
1 pc	Bootlid lock cable	\$	35.00	x n n ✓
1 pc	Bootlid striker	\$	21.00	R ✓
1 pc	Bootlid emblem	\$	27.00	re ✓
1 pc	Bootlid CRDi	\$	29.00	re ✓
1 pc	Boot lid rubber weatherstrip	\$	96.00	re ✓
1 pc	Boot lid lower garnish	\$	290.00	an ✓
2 pcs	Bootlid hinges @ \$66.00	\$	132.00	R ✓
1 pc	End panel	\$	250.00	bt ✓
1 pc	End panel inner garnish	\$	74.00	de ✓
1 pc	Rear bumper	\$	696.00	de ✓
1 pc	Rear bumper lower cover	\$	206.00	de ✓
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	re ✓
1 pc	Rear bumper inner sponge	\$	114.00	re ✓
1 pc	Rear bumper reinforcement	\$	607.00	bt ✓
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00	? de ✓
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	? ✓ bt
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	? ✓ bt
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	x n n ✓
2 pcs	n/s & o/s tail lamp @ \$421.00	\$	842.00	o/s - re n n ✓
2 pcs	n/s & o/s reflector @ \$350.00	\$	700.00	x n n ✓
		\$	5,667.00	4687 ✓
Less 10%		\$	566.70	4218.30 ✓
		\$	5,100.30	

S/NETT

1 set	Rear bumper clips	\$	48.00	30 n n ✓
1 set	End panel inner garnish clips	\$	30.00	20 n n ✓
1 set	Bootlid inner trim clips	\$	52.00	20 n n ✓
1 set	Bootlid lower garnish clips	\$	60.00	20 n n ✓
1 set	Bootlid stickers	\$	100.00	re ✓
1 set	Reverse sensor	\$	280.00	200 n n ✓

390

6-Jul-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6994 G

Sundry	\$	50.00 ²⁰
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 ³⁰
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 ⁶⁰
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, Including knock-out, straighten, repair, reshape and adjust of the the same	\$	950.00 ⁶⁰⁰
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel.	\$	800.00 ⁶⁰⁰
To apply rustproofing on the repaired and replaced panels.	\$	150.00 ³⁰
	\$	<u>7,920.30</u>
		1340.

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Taufik 97495764
wp'
8/7/20 @ 4pm
humpson 04 days
Review after repair
taufik@lkhauts.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4218.30
390
1340
5948.30
4/4 4750