

LBS AUTOMOTIVE APPRAISAL PTE. LTD.

Co. Reg. No. 201408536E

Block 8 Kensington Park Drive #01-07

Singapore 557323

Telephone: 62832866, 62816690 Facsimile: 62818748, 62832166

AUTOMOBILE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

OUR REFERENCE: LBS/AXA/TP/PRI/19/11/M028

REFERENCE: THIRD PARTY CLAIM- PRE-REPAIR INSPECTION

VEHICLE NUMBER : SMG 7105U POLICY NUMBER : N.A.
ACCIDENT DATE : 01.11.2019 CLAIM NUMBER : S9M025W9 - SGQ 2703U

PARTICULARS OF DAMAGED VEHICLE:

MAKE : VOLKSWAGEN NEW GOLF MODEL : 2009
COLOUR : WHITE MILEAGE KM : 123827
ENGINE CAPACITY : 1390CC V.I.N. : WVVZZZ1KZ9W572839

STATIC CHECKS: GENERAL CONDITION: GOOD

STEERING: SERVICEABLE

BRAKES: SERVICEABLE

TYRE CONDITIONS: SIZE: 235/40R18

FRONT N/S : 50% FRONT O/S : 50%
REAR N/S : 50% REAR O/S : 50%

Percentages denote the remaining estimated life of the tyre threads

ESTIMATED NORMAL PERIOD FOR REPAIR: 05 WORKING DAYS
IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORIZED REPAIRS.

GENERAL DAMAGES

The impact was confined to the off side rear broadside portion of the vehicle.

REMARKS

No estimate provided by workshop.

Economical Repair Value \$17,070.00 (Estimated Market Value \$28,000.00 less LTA rebate \$10,930.00)

Basing on visual inspection of the damage during the pre-repair survey, we opined the estimated repair cost to be in the region of \$2,000.00.

This pre-repair inspection was conducted on a "WITHOUT PREJUDICE" basis.

Vehicle inspected by : Mr Stan See Chew Seng
Date of Inspection : 18.11.2019
Surveyed at : 8 Paragon Pte Ltd
Date of Report : 09.12.2019