

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 15 Jul 2020

Preliminary Advice

Insured Vehicle No	: SJH4858E		
TP Vehicle No	: SKE1015U	Accident Date	: 06/07/2020
Make	: VOLKSWAGEN TOURAN SPORT	Assignment Date	: 08/07/2020
Date of Inspection	: 08/07/2020	Est. Duration of Repair	: 7 days
Inspection At	: H C Auto Pte Ltd (HQ) 160 Sin Ming Drive, #05-09 Sin Ming Auto City Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,277.50
Revised Amount	:S\$	10,422.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,422.25
Lump Sum Repair	:S\$	4,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP