

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 07.07.2020
Time: 16:50:50
Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS: CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305409753
REGN NO : SHA8277R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 07.07.2020 14:30
ACCIDENT DATE : 06.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	de✓
0002	04-01-0103-0637-G	I40VC BRKT ASSY-FR BPR UP	1	22.40	20.00	17.92	?
0003	04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	?
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10	22.00	20.00	17.60	de✓
0005	04-01-0103-0781-A	I40VC LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40	?
0006	04-01-0103-0574-A	I40VC PANEL-FENDER LH+	1	663.00	20.00	530.40	ht✓
0007	04-01-0103-0657-G	I40V2 GUARD ASSY-FR WHEEL	1	174.90	20.00	139.92	art✓
0008	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	112.50	20.00	90.00	de✓
0009	03-01-0103-0098-G	I40VC WHEEL ASSY-STEEL	1	325.30	20.00	260.24	Ky

SUB-TOTAL : 3,027.92

JOB NATURE

0000 L PANEL BEATING(rep. bonnet & v.mirror
0001 23-502 SPRAYPAINT ON AFFECTED AREA

700.00 420.

650.00 400.

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 07.07.2020
Time: 16:50:50
Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305409753
REGN NO : SHA8277R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 07.07.2020 14:3
ACCIDENT DATE : 06.07.2020

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002 17-01 CHECK ALL LIGHTING	50.00		30		
0003 20-00 TUFF COAT ON AFFECTED PARTS.	50.00		30		
0004 20-08 ADJUST FRONT WHEEL ALIGNMENT	120.00		80		
SUB-TOTAL :					1,570.00
TOTAL :					4,597.92

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tanfkin 97445749
WP' 8/7/20 @ 4pm
Lumpsum
Resurvey after repair
tanfkin@lkhauto.com
02-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date/Time: 07.07.2020 16:03

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO.:305409753

OWNER
CITYCAB PTE LTD
7010070
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188 (O)
(R)
(P)


OUNT CARD NO.

AIG
JOB DESCRIPTION

REGN NO: SHA8277R	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 07.07.2020 14:30
YR OF MANU. 25.08.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU093531	COMPLETION DATE/TIME:

Accident Date: 06.07.2020
NATURE: 3P 06.07.2020

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Engagement Slip

Exit Pass

Vehicle No.:

SHA8277R

Name of Service Advisor

To be kept by Security Guard

Date

Service Advisor

Signature/Date

Returned to Service Reception upon collection