

China - (L/sum)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 06.07.2020

Time: 10:32:38

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305409157
REGN NO : SH 7543L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.05.2014
DATE/TIME IN : 04.07.2020 12:18
ACCIDENT DATE : 03.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	de ✓
0002 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	de ✓
0003 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	new ✓
0004 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	?
0005 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	?
0006 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	new ✓
0007 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	0.20	135.70	new ✓

SUB-TOTAL : 1,708.82

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	200
0002 17-01	CHECK ALL LIGHTING	50.00	30

0003 L ^{Replace reverse sensor.}
LUBRICATE LOCK THINGS & HOOK LATCH

80.00 R 30

Tanjin 97495749

'wp'

6/7/20 R 330

2 days

lump sum

Resurvey after repair.

Tanjin @ lkhant.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PT. 0

COMFORTDELGRO ENGINEERING PTE LTD

Date: 06.07.2020

Time: 10:32:38

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305409157
REGN NO : SH 7543L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 14.05.2014
DATE/TIME IN : 04.07.2020 12:1
ACCIDENT DATE : 03.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 730.00

TOTAL : 2,438.82

MVA NAME & SIGNATURE

DATE: 6/7/20

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

201 Braddell Road Singapore 579701
Hotline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Luyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 122286

24 Seneca Loop Singapore 758146
7 Selegie Road Singapore 118291
501 Yishun Industrial Park Singapore 768050

Date/Time: 06.07.2020 10:16

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO: 305409157

OMER
IS COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)

REGN NO: SH 7543L	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 04.07.2020 12:18
YR OF MANU. 14.05.2014	TARGET DATE
CHASSIS CODE KMHLB41UMEU053844	COMPLETION DATE/TIME


DUNT CARD NO.

JOB DESCRIPTION

Accident Date: 03.07.2020

NATURE: 3P 03.07.2020

S/NO LABOR CODE DESCRIPTION



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Damage Report Slip

Exit Pass

No.: SH 7543L

JU CHINA LKK

Vehicle No.:

SH 7543L

Service Advisor

Signature/Date

Name of Service Advisor

Date