

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40373

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0475/2020/NS
Date : 6-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Leong Kok Meng
Address	:	Blk 617 Woodlands Ave 4 #10-553 Singapore 730617
Telephone	:	HP +65 81861284
Type of Claim	:	Own Damage Claim
Policy No.	:	2100498857-03
Vehicle No	:	SLK 7949 S
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Jan-17
Engine No	:	CHZ 142329
Chassis No	:	WAUZZZ8V8H1016421
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	4-Jul-20
Place of Accident	:	Pasir Ris Flyover

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLK 7949 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer lhs headlight control units and power modules. To carry out calibration.	S/N \$ 350.00	X
2	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	X
3	To dismantle and renew front bumper. To repair bonnet. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 3,850.00	500
4	To respray front bumper and bonnet.	\$ 2,000.00	1100
5	To carry out diagnostic check.	S/N \$ 192.00	✓

SUB TOTAL LABOUR CHARGES

: \$ 7,592.00

Premium Automobiles

55 Ubi Road 1., Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>Defend -</i>	\$	1,894.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	176.00	+
3	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	\$	36.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>Crashd</i>	\$	151.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	505.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	\$	280.00	+
7	FRONT BUMPER COVER TRIM - LH <i>new</i>	\$	153.00	+
8	WHEEL HOUSING LINER ADAPTER - LH <i>new</i>	\$	36.00	+
9	RADIATOR GRILLE <i>Crashd</i>	\$	1,338.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT ?	\$	180.00	?
11	AIRCON STICKER <i>2 new</i>	NEC \$	7.00	✓
12	CAUTION SIGN STICKER	NEC \$	13.00	✓
13	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$	681.00	?
14	FRONT BUMPER FOAM FILLER PIECE ?	\$	178.00	?
15	FOAM FILLER PIECE COVER ?	\$	115.00	?
16	TOP FOAM FILLER PIECE COVER ?	\$	115.00	?
17	FRONT BUMPER AIR GUIDE GRILLE - LH <i>missing</i>	\$	177.00	✓
18	SIGNAL HORN RETAINER - LH HIGH TONE <i>new</i>	\$	188.00	+
19	LED HEADLIGHT - LH <i>new</i>	\$	5,193.00	+
20	LIFT CYLINDER - LH / RH <i>new</i>	2 \$	268.00	+
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$11,684.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 7949 S

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	LIFT CYLINDER HOSE <i>3 m</i>	\$ 64.00	+
22	WASH WATER RESERVOIR	\$ 190.00	+
23	LOCK CARRIER <i>3 m</i>	\$ 685.00	+
24	AIRCON CONDENSER	\$ 519.00	+
25	READY MIX COOLANT <i>10 l</i>	\$ 86.00	+
26	RADIATOR AIR GUIDE - LH / RH ?	2 \$ 46.00	?
27	RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>	\$ 12.00	+
28	FRONT NO PLATE <i>Dented</i>	S/N \$ 60.00	✓
29	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 13,646.00
TOTAL LABOUR CHARGES		:	\$ 7,592.00
GRAND TOTAL		:	\$ 21,238.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adrian
08/07/20.

Not Authorised, 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant