

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20007113/UBA3Q2

Date: 13/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : FBL4371R	Insured Vehicle No :	SHD4733B
Date of Loss: 25/06/2020	Nature of Claim: TP	Claim No: MCT20060302

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL4371R		
Make & Model:	PIAGGIO VESPA SPRINT 150, 155cc SPORT	Engine No:	M814M1001851
Reg. Date:	13/10/2016 (Man. Year: 2015)	Chassis No:	ZAPM8140100001204
Colour:	Grey	Odometer:	28430 km
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R12	Rear Tyre Size:	120/70 R12
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	929.00	564.00	365.00	39.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	430.00	60.00	370.00	86.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,359.00	624.00	735.00	54.08
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
Nett Liability (S\$)		684.00		

INSPECTION

Date of Assignment:	08/07/2020	
Date Inspected:	08/07/2020 Inspected At:	Erofia Motor Trading Pte Ltd (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-62 Singapore 417883
Estimated Period of Repair:	1.0 days	

Adjuster: MARCUS CHUA

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 17 Sep 2020)	
Parts:	N/A	PIAGGIO VESPA SPRINT 150 155cc SPORT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL4371R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Serviceable	90.00 FL	*- FL
2	2		*REAR NUMBER PLATE	Bent (1 PCS ONLY)	28.00 FS	*14.00 FS
3	1		*REAR BOX	Cracked	820.00 FS	*550.00 FS
					Sub Total (\$\$)	938.00 564.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	9.00 0.00
					Total Parts (\$\$)	929.00 564.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE	New	50.00	0.00
2	TO PROVIDE LABOUR	New	220.00	60.00
3	TO RE-SPRAY PAINTING	New	160.00	0.00
Gross Labour Cost (\$\$)			430.00	60.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >