



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2106443

INV Date 15/09/2021

Reference CC4/LPC20007123/Aea3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SFY 8321T
Insured Veh. SGY 6575D
Claim No. 19/20/20/VP05/023450
Policy No. Z19VP05024590
Accident Date 07/07/2020
Inspection Date 08/07/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC20007123/Aea3q2	
			Date: 15/09/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGY 6575D	Veh. Inspected	SFY 8321T	
Policy No.	Z19VP05024590	Coverage (\$)	0.00	
Claim No.	19/20/20/VP05/023450	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	08/07/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	RU11320123	Colour	GREY	
Odometer	11646 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/07/2020	Inspection Date	08/07/2020	
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFY 8321T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DISTORTED	880.00	880.00
1	FRONT FOG LAMP COVER	DEFORMED	45.00	45.00
1	BONNET	NOT NECESSARY	850.00	-
1	BONNET HINGE -LEFT	NOT NECESSARY	75.00	-
1	BONNET HINGE-RIGHT	NOT NECESSARY	75.00	-
1	HEADLAMP -RIGHT	CRACKED	2,400.00	1,784.00
1	HEADLAMP BRACKET -RIGHT	CRACKED	120.00	55.00
1	FRONT DOOR -RIGHT	NOT NECESSARY	1,200.00	-
1	WHEEL ARCH -FRONT RIGHT	CUT	120.00	120.00
1	MUDGUARD -FRONT RIGHT	NOT NECESSARY	110.00	-
1	FOG LAMP (ADDITIONAL)	NOT NECESSARY	320.00	-
1	FRONT BUMPER LOWER CLIPS (ADDITIONAL)	DEFORMED	290.00	290.00
1	WIPER TANK (ADDITIONAL)	DEFORMED	90.00	90.00
1	BUMPER BRACKET -RIGHT (ADDITIONAL)	NOT NECESSARY	55.00	-
1	FENDER BEAM -RIGHT (ADDITIONAL) (NPA)	TO REPAIR SEE LABOUR	-	-
1	FENDER -RIGHT (ADDITIONAL) (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-	-652.80
			6,630.00	2,611.20
	<u>SPECIAL NETT ITEMS</u>			
1	TYRE -FRONT RIGHT (SN)	NOT NECESSARY	180.00	-
1	BUMPER CLIPS (SN)	NECESSARY	100.00	30.00
1	RIM -FRONT RIGHT (SN)	NOT NECESSARY	350.00	-
			630.00	30.00
	<u>LABOUR</u>			
	PAINT PROTECTION .		400.00	200.00
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA.		600.00	400.00
	TO PANEL BEAT & RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.INCLUSIVE OF THE REPAIR OF FENDER BEAM -RIGHTAND FENDER -RIGHT.		800.00	300.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE.	NOT NECESSARY	150.00	30.00
	ANTI RUST TREATMENT .		120.00	-
	WHEEL BALANCING & ALIGNMENT.		180.00	80.00
	PROGRAMMING OF H/LAMP .		350.00	100.00
			2,600.00	1,110.00
GRAND TOTAL			9,860.00	3,751.20
RECOMMENDED COST OF REPAIRS				3,751.20

Report Ref No. CC4/LPC20007123/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFY 8321T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFY 8321T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFY 8321T

RE-INSPECTION

