



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 2016051232

Estimated repair checklist

Vehicle Registration No.: SK59035K
Vehicle Make/Model: Toyota Corolla Altis
Chassis number: MR053REH104528483

TP Chian
Thibby

QTY	Parts	Prices \$
		758
1	Bootlid <i>Bulb</i>	801.10 ✓
1	Bootlid centre emblem	62.10 ✓
1	Bootlid "Corolla" emblem <i>new</i>	60.30 ✓
1	Bootlid "Altis" emblem	54.10 ✓
1	Bootlid lock <i>new</i>	379.20 ✓
1	Bootlid lock catch <i>new</i>	86.00 ✓
1	Bootlid RH lamp assy <i>new</i>	374.45 ✓ 328.10
1	Bootlid inner black sponge gasket <i>new</i>	23.00 ✓
1	Bootlid LH lamp assy <i>new</i>	374.45 ✓ 328.10
1	Bootlid LH black sponge gasket <i>new</i>	23.00 ✓
1	Bootlid RH hinge <i>new</i>	89.50 ✓
1	Bootlid LH hinge <i>new</i>	89.50 ✓
1	Bootlid chrome moulding <i>new</i>	244.00 ✓
2	Bootlid number plate lamps assy <i>new</i>	56.00 ✓
1	Bootlid inner trim <i>new</i>	181.95 ✓
10	Bootlid inner trim clips <i>new</i>	50.00 ✓
1	Rear bumper <i>new</i>	581.90 ✓
10	Rear bumper clips <i>new</i>	55.00 ✓ 30
1	Rear bumper RH side retainer <i>new</i>	67.00 ✓
1	Rear bumper LH side retainer <i>new</i>	67.00 ✓
1	Rear bumper RH side holder <i>new</i>	72.00 ✓
1	Rear bumper LH side holder <i>new</i>	72.00 ✓
1	Rear bumper RH reflector <i>new</i>	141.45 ✓
1	Rear bumper LH reflector <i>new</i>	141.45 ✓
1	Rear bumper reinforcement <i>new</i>	398.70 ✓
1	Rear bumper reinforcement RH bracket <i>new</i>	165.00 ✓
1	Rear bumper reinforcement LH bracket <i>new</i>	165.00 ✓
1	Rear bumper RH reverse sensor <i>new</i>	265.30 ✓ 200.00
1	Rear bumper LH reverse sensor <i>new</i>	265.30 ✓
2	Rear bumper reverse sensor holder <i>new</i>	242.20 ✓
1	RH taillamp assy <i>new</i>	400.50 ✓
1	RH taillamp black sponge gasket <i>new</i>	25.00 ✓
1	RH taillamp lower bracket <i>new</i>	88.70 ✓
1	RH taillamp panel <i>new</i>	374.55 ✓
1	LH taillamp assy <i>new</i>	400.50 ✓
1	LH taillamp black sponge gasket <i>new</i>	25.00 ✓
1	LH taillamp lower bracket <i>new</i>	88.70 ✓



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

- 1 LH taillamp panel *new*
- 1 End panel *Dented*
- 1 End panel inner garnish *crushed*
- 1 Spare tyre top board *new*
- 1 Rear fender RH inner trim
- 10 Rear fender RH inner trim clips
- 1 Rear fender LH inner trim
- 10 Rear fender LH inner trim clips

374.55

781.90

185.99

485.10

338.00

50.00

338.00

50.00

4381.10

3285.82

SN 200

9,654.44

-25% 2,413.61

7,240.83

Special Nett

- 1 Rear number plate *new*

40.00

Labour charges

Remove and replace the above listed parts, knock straighten and reshape, cut and weld body panel parts where necessary, re-position and re-align, replacement parts to the original position including adjustment.

~~1,000.00~~ 700

Putty and respray on affected areas and panels

~~1,200.00~~ 700

Check wiring and lighting system on affected areas

~~80.00~~ 30

Apply rust proofing on affected areas and panels

1600

~~100.00~~ 60

Remove and replace rear inner trims and garnish

~~280.00~~ 60

Remove and replace rear reverse sensors

~~80.00~~ 50

2,740.00

10,020.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged panel during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

Total: 5085.82

L/S: AK.

Adm Lin.
4/5 09/07/20
06 Days