

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40750

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0481/2020/NS
Date : 8-Jul-20

Vehicle IN workshop. Please arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Acmea Cooling System & Engineering Pte Ltd
Address : 15 Yishun Industrial Street
#03-21/22
Singapore 768091
Telephone : (HP) +65 96795122
Type of Claim : Own Damage Claim
Policy No. : 1900000222-01
Vehicle No : **SKG 1989 Z**
Model Code : Audi A5 Sportsback 2.0 TFSI Qu
Model / Year : 28/1/2019
Engine No : CVK 073959
Chassis No : WAUZZZF58KA012976
Mileage : 35374
Date In : 8-Jul-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Jul-20
Place of Accident : Gambas Avenue

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKG 1989 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00	✓ ✓
2	To remove and transfer rhs headlight control unit and power module. To carry out calibration.	S/N \$ 400.00	250 ✓
3	To dismantle and reinstall both front door panel trims. To remove and reinstall rhs wing mirror assys.	S/N \$ 800.00	X, 360 H.S.
4	To remove and reinstall aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00	✓ ✓
5	To dismantle and renew front bumper and bonnet. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 4,800.00	2250 ✓
6	To respray front bumper, bonnet, hinges, rhs front door and lhs front door.	\$ 4,500.00	1650 3200 H.S.
7	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$ 384.00	192 H.S.
TOTAL LABOUR CHARGES		: \$ 12,564.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 1989 Z

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remarks
1	RADIATOR GRILLE <i>Here cracked.</i>	\$ 2,190.00	+ 1840
2	ULTRASOUND SENSOR SUPPORT - LH / RH <i>Here Damaged.</i>	\$ 98.00	+ 80.80
3	RADIATOR GRILLE COVER - UPPER <i>new Not new</i>	\$ 178.00	? X
4	FRONT BUMPER TOP COVER <i>Cracked</i>	\$ 120.00	✓ 100.40
5	CAUTION SIGN STICKER <i>NEC</i>	NEC \$ 13.00	✓ 10.80
6	AIRCON STICKER <i>NEC</i>	NEC \$ 7.00	✓ 5.68
7	QUATTRO INSCRIPTION <i>new</i>	\$ 102.00	+
8	BONNET <i>Distorted</i>	\$ 2,682.00	✓ 2253.60
9	BONNET ATTACHMENT PARTS <i>new</i>	\$ 116.00	? X
10	BONNET LID HINGE - LH / RH <i>new</i>	2 \$ 790.00	? X
11	BONNET IMPACT PROTECTION - LH / RH / CENTRE <i>new</i>	3 \$ 78.00	✓ 64.88
12	BONNET SOUND ABSORBER <i>new</i>	\$ 323.00	+
13	FENDER LEDGE COVER - INNER <i>new</i>	\$ 34.00	? X
14	FENDER LEDGE COVER - OUTER <i>new</i>	\$ 15.00	? X
15	BONNET STRIKER - RH <i>Best</i>	\$ 47.00	✓ 39.44
16	BONNET LID LOCK <i>new</i>	\$ 202.00	+
17	BONNET LID LOCK CABLE <i>new</i>	\$ 69.00	+
18	LED HEADLIGHT - RH <i>Cracked</i>	\$ 7,438.00	✓ 6249.60
19	MAIN LIGHT ELECTRONICS POWER MODULE <i>new</i>	\$ 714.00	? X
20	LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>	\$ 707.00	? X
SUB TOTAL SPARE PARTS		:	\$ 15,923.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 1989 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	LED WITH HEAT SINK - RH <i>Not new</i>	\$ 1,086.00	? <i>X</i>
22	HEADLIGHT HOSE <i>new</i>	\$ 34.00	+
23	FRONT BUMPER <i>Del'd</i>	\$ 2,142.00	✓ <i>1800.80</i>
24	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 383.00	+
25	LOCK CARRIER <i>Del'd</i>	\$ 956.00	✓ <i>803.20</i>
26	READY MIX COOLANT <i>new</i>	\$ 169.00	✓ <i>141.44</i>
27	RADIATOR AIR GUIDE - UPPER <i>Not new</i>	\$ 15.00	? <i>X</i>
28	DOOR TRIM - LH / RH <i>new LH new</i>	2 \$ 300.00	<i>X</i> <i>125.60</i>
29	FRONT NO PLATE <i>new</i>	S/N \$ 60.00	+
30	SUNDRIES <i>new</i>	\$ 300.00	? <i>2.24</i>
TOTAL SPARE PARTS		: \$ 21,368.00	
TOTAL LABOUR CHARGES		: \$ 12,564.00	
GRAND TOTAL		: \$ 33,932.00	<i>37811</i>

All charges are not inclusive of GST.
Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

(S) 3879

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian S*
Surveyed Date : *08/07/20*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 08 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant