

Premium Automobiles

55, Ulu Road 3, Singapore 408699
Tel: 6366 7121 Fax: 6341 1181

Telefax

Estimated Labour Charges for Accident Vehicle. SKG 1989 Z

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00 ✓	
2	To remove and transfer rhs headlight control unit and power module. To carry out calibration.	S/N \$ 400.00 250.	sls
3	To dismantle and reinstall both front door panel trims. To remove and reinstall rhs wing mirror assys.	S/N \$ 800.00 X. 360 (LHS)	
4	To remove and reinstall aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 ✓	
5	To dismantle and renew front bumper and bonnet. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 4,800.00 2250.	
6	To respray front bumper, bonnet, hinges, rhs front door and lhs front door.	\$ 4,500.00 1650	
7	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$ 384.00 ✓ ?	
TOTAL LABOUR CHARGES		: <u>\$ 12,564.00</u>	

Car-in

13/7/2010

Kiam / Hang

wip: 40750

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel. 6366 2323 Fax. 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 1989 Z

8 days

		Damaged Parts & Prices		Remarks
S/N	Parts Description	S/Nett		
1	RADIATOR GRILLE new Crashed	\$	2,190.00	✓
2	ULTRASOUND SENSOR SUPPORT - LH / RH new	2 \$	98.00	✓
3	RADIATOR GRILLE COVER - UPPER new ?	\$	178.00	?
4	FRONT BUMPER TOP COVER Crashed	\$	120.00	✓
5	CAUTION SIGN STICKER ?	NEC \$	13.00	✓
6	AIRCON STICKER new NEC	NEC \$	7.00	✓
7	QUATTRO INSCRIPTION new	\$	102.00	✓
8	BONNET Distorted	\$	2,682.00	✓
9	BONNET ATTACHMENT PARTS ?	\$	116.00	?
10	BONNET LID HINGE - LH / RH ?	2 \$	790.00	?
11	BONNET IMPACT PROTECTION - LH / RH / CENTRE new	3 \$	78.00	✓
12	BONNET SOUND ABSORBER new	\$	323.00	✓
13	FENDER LEDGE COVER - INNER ?	\$	34.00	?
14	FENDER LEDGE COVER - OUTER ?	\$	15.00	?
15	BONNET STRIKER - RH new	\$	47.00	✓
16	BONNET LID LOCK ?	\$	202.00	✓
17	BONNET LID LOCK CABLE new	\$	69.00	✓
18	LED HEADLIGHT - RH Crashed	\$	7,438.00	✓
19	MAIN LIGHT ELECTRONICS POWER MODULE ?	\$	714.00	?
20	LIGHT CONTROL SYSTEM CONTROL UNIT ?	\$	707.00	?
SUB TOTAL SPARE PARTS		:	\$ 15,923.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKG 1989 Z

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	LED WITH HEAT SINK - RH ?	\$ 1,086.00	?
22	HEADLIGHT HOSE <i>new</i>	\$ 34.00	✓
23	FRONT BUMPER <i>del d</i>	\$ 2,142.00	✓
24	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 383.00	✓
25	LOCK CARRIER <i>new</i>	\$ 956.00	✓
26	READY MIX COOLANT <i>new</i>	\$ 169.00	✓
27	RADIATOR AIR GUIDE - UPPER ?	\$ 15.00	?
28	DOOR TRIM - LH / RH <i>new LH new</i>	2 \$ 300.00	150 <i>HLG.</i>
29	FRONT NO PLATE <i>Not in spec</i>	S/N \$ 60.00	✓
30	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 21,368.00	
TOTAL LABOUR CHARGES		: \$ 12,564.00	
GRAND TOTAL		: \$ 33,932.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.