

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Veron

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0481/2020/NS

Date

13-Jul-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SKG 1989 Z

Model No

Audi A5 Sportsback 2.0 TFSI Qu

Quantity	Description	Unit Price	Amount
Parts			
1	Front fender emblem trim RHS <i>new</i>	\$ 150.00	<i>—</i>
2	Bracket lock carrier <i>could</i>	\$ 129.00	<i>—</i>
Labours			
1	To repair rhs front fender.	\$ 800.00	<i>250</i>
2	To respray rhs front fender.	\$ 1,000.00	<i>550</i>
3	To repair rhs upper A-pillar.	\$ 800.00	<i>250</i>
4	To respray rhs upper A-pillar.	\$ 1,000.00	<i>550</i>
TOTAL		\$ 1,800.00	3879.00

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Lj

13/07/20

fls

add 3 days