

CG/AIG20007131/Ada3

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date :07/07/2020

Reference: CHEVROLET

Make: CRUZE

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SJK1808A

CHASSIS NO.: KL1JA69E9GK351285

ENGINE NO.: F16D4161450388

Name of insured : TAN BENG KOON

Date of accident.: 07/07/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	RR TAILLAMP PANEL RH <i>new</i>	\$ 322.00
2	1	RR FENDER INNER TRIM LH <i>new</i>	\$ 388.00
3	1	RR FENDER INNER TRIM RH <i>new</i>	\$ 388.00
4	1	RR BUMPER <i>Deformed</i>	\$ 1,456.00
5	1	RR BUMPER CHROME MLDG RH <i>new</i>	\$ 152.00
6	1	RR BUMPER CHROME MLDG LH <i>new</i>	\$ 152.00
7	1	RR BUMPER CHROME MLDG CENTRE <i>new</i>	\$ 205.00
8	1	RR BUMPER REINFORCEMENT <i>new</i>	\$ 736.00
9	1	RR BUMPER SIDE RETAINER LH(INNER) <i>new</i>	\$ 116.00
10	1	RR BUMPER SIDE RETAINER LH(OUTER) <i>new</i>	\$ 116.00
11	1	RR BUMPER SIDE RETAINER RH(INNER) <i>new</i>	\$ 116.00
12	1	RR BUMPER SIDE RETAINER RH(OUTER) <i>new</i>	\$ 116.00
13	1	RR BUMPER CENTRE RETAINER <i>new</i>	\$ 130.00
14	4	RR BUMPER REVERSE SENSOR <i>2 pieces dmd</i>	\$ 860.00
15	4	RR BUMPER REVERSE SENSOR RUBBER SEAL <i>new</i>	\$ 52.00
16	1	RR BUMPER REVERSE WIRE HARNESS <i>new</i>	\$ 336.00
17	1	RR BUMPER TOW COVER <i>new</i>	\$ 96.00
18	2	RR NUMBER PLATE LAMP <i>new</i>	\$ 150.00
19	1	RR BOOTLID <i>Dented</i>	\$ 1,973.00
20	1	RR BOOTLID WHEATHER STRIP <i>cut</i>	\$ 214.00
21	2	RR BOOTLID STOPED <i>new</i>	\$ 24.00
22	1	RR BOOTLID INSULATOR <i>new</i>	\$ 288.00
23	1	RR BOOTLID LOGO <i>new</i>	\$ 165.00
24	1	RR BOOTLID EMBLEM CHEVROLET <i>new</i>	\$ 82.00
25	1	RR BOOTLID EMBLEM CRUZE LS <i>new</i>	\$ 80.00
26	1	RR BOOTLID LOCK <i>Dmd</i>	\$ 286.00
27	1	RR BOOTLID LOCK COVER <i>cut</i>	\$ 38.00
28	1	RR BOOTLID LOCK KEYLESS SENSOR <i>cut</i>	\$ 167.00
29	1	RR BOOTLID HINGE RH	\$ 176.00
30	1	RR BOOTLID HINGE LH	\$ 176.00
31	1	RR BOOTLID LAMP RH <i>new</i>	\$ 401.00
32	1	RR BOOTLID LAMP LH <i>new</i>	\$ 401.00
33	1	RR TAILLAMP LH	\$ 850.00
34	1	RR TAILLAMP RH	\$ 850.00
35	1	RR END PANEL <i>new</i>	\$ 996.00
36	1	RR END PANEL TOP GARNISH <i>cut</i>	\$ 267.00
37	1	RR SPARE TYRE PANEL BOARD <i>new</i>	\$ 473.00

6817

6135.30

--	--	--	--	--

Parts Total: \$ 13,794.00
Less 10%: \$ 1,379.40
Total : \$ 12,414.60

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 2,000.00
2	Carry out spray painting on affected area, RR BUMPER, RR BOOTLID, RR END PANEL, RR SPARE TYRE PANEL, RR FENDER LH, RR FENDER RH	\$ 1,200.00
3	To disconnect rear wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00
4	Remove and refix interior trim, seat cushion/upholstery, roof lining, seatbelt, etc	\$ 200.00
5	To remove and refix reverse sensor and conduct test	\$ 120.00
6	To remove and refix reverse camera and conduct test	\$ 120.00
7	To conduct transfer of parts from old bootlid to new bootlid	\$ 180.00
8	To remove and replace exhaust pipe for assist repair	\$ 200.00
9	To conduct anti rust of under carriage tuff coat	\$ 100.00
10	To conduct water leakage test after repairs of vehicle	\$ 60.00
11	To perform diagnostic test & reset faulty code	\$ 220.00

Others

No.	Other Description	Price (SGD)
1	RR BUMPER CLIP	\$ 40.00
2	RR BOOTLID INNER TRIM CLIP	\$ 40.00
3	RR FENDER INNER TRIM CLIP	\$ 40.00
4	RR FENDER INNER SHIELD CLIP	\$ 40.00
5	RR END PANEL TOP GARNISH CLIP	\$ 20.00
6	RR REVERSE CAMERA	\$ 300.00
7	RR NUMBER PLATE	\$ 65.00

TOTAL: 545.00
GRAND TOTAL : 17,479.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Kelvin Chew
HP: 8292 5595

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 7790.30

(P/R)

Adrian
08/07/20
DA Days