

ASS. REC. BY:

REF: MG / 2000 7133/Ke

C


Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s City Auto  
 of \_\_\_\_\_  
 Insured: 699N  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Veh No: GBH 1604K Yr Regn: 02, 18  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toy Hiace c.c. 2982  
 Colour: M. Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 55466 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: K01420 · 0228318  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: MITS/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195R15XJ  
 R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 9 mm R/Bal. 6 mm  
 L/Bal. 9 mm L/Bal. 6 mm  
 D.O.A. 6/7/20 D.O.I. 9/7/2020  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>17/7</u>	<u>@ 4590.94 Confirmed</u>

Date/Time, File Pass to?  : Preil. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trlp: \_\_\_\_\_

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech Invs (\$)  
 : Weekend (\$)

Survey Fee:

Transportation	_____
\$ - RS, SI	_____
_____	_____
_____	_____
_____	_____
TOTAL	_____

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202007-000241(00)

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY #07-16

SINGAPORE 079120

Date : 08/07/2020

Vehicle No. : GBH1604K

Make/Model : TOYOTA HIACE

Mileage (km) : 0

Chassis No. : KDH201-0228318

Accident Date : 06/07/2020 00:00:00

Claim No. : SJL1283L

Reference : JO202007-0299

Policy No. : 5097962989-02

Contact : -

Fax No. : 6880 4838

*Not with order*

*Remove B4 paint*

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

*B4590.94*

*5 days*

### LIST ITEMS :

1	Tailgate	1.0	2,021.70	2,021.70 ✓
2	Tailgate lock	1.0	265.74	265.74 ✓
3	Tailgate lock cover	1.0	122.30	122.30 ✓
4	Tailgate logo	1.0	61.70	61.70 ✓
5	Tailgate emblem - Hiace	1.0	49.50	49.50 ✓
6	Tailgate emblem - super GL	1.0	43.67	43.67 ✓
7	Tailgate outer chrome moulding	1.0	240.71	240.71 ✗
8	Tailgate weatherstrip	1.0	402.70	402.70 ✗
9	Tailgate striker	1.0	122.47	122.47 ✗
10	Tailgate inner trim	1.0	298.40	298.40 ✗
11	Rear bumper	1.0	396.90	396.90 ✓
12	Rear bumper retainer	2.0	40.33	80.66 ✓
13	Rear Bumper clips	12.0	4.21	50.52 ✓
14	Rear keyless entry antennae	1.0	212.67	212.67 ✗
15	Rear step panel	1.0	360.98	360.98 ✓
16	Rear end panel outer	1.0	315.95	315.95 ✓
17	Rear end panel inner	1.0	891.75	891.75 ✗
18	Rear end panel top garnish	1.0	178.30	178.30 ✓
19	Tail lamp	2.0	332.75	665.50 ✗
20	Tail lamp lower cover	2.0	141.66	283.32 ✗

List Total :

7,065.44

25% Discount S\$

1,766.32

5,299.12

### SPECIAL NET :

1	Tailgate sticker - 70 Km/h	1.0	10.00	10.00 ✓
2	Tailgate sticker 6 pax	1.0	10.00	10.00 ✓
3	Glass sealant	1.0	40.00	40.00 ✓

SPECIAL NET Total S\$:

60.00

### LABOUR :

* To remove and refit rear windscreen glass	1.0	100.00	100.00 ✓
* To remove and refit rear trims and upholstery	1.0	120.00	120.00 60
* To check wiring and lighting	1.0	50.00	50.00 20
* To spray rubberized under-coating	1.0	150.00	150.00 60

CONTINUE NEXT PAGE

2960.94  
~~2968.44~~  
1630  
~~4588.44~~



# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643  
TEL: 6453 1235, 6452 0850 FAX: 6453 7944  
24hrs Towing Services Tel 9823 9898  
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

**Estimate : QUOT202007-000241(00)**

AIG ASIA PACIFIC INSURANCE PTE. LTD  
NO. 78  
SHENTON WAY #07-16  
SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

Date : 08/07/2020  
Vehicle No. : GBH1604K  
Make/Model : TOYOTA HIACE  
Mileage (km) : 0  
Chassis No. : KDH201-0228318  
Accident Date : 06/07/2020 00:00:00  
Claim No. : SJL1283L  
Reference : JO202007-0299  
Policy No. : 5097962989-02

S/No	Particular	Quantity	Unit Price	Amount S\$
	* To supply panel sealant and to seal off all weld spot seam and gaps	1.0	150.00	150.00 <i>300</i>
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	900.00	900.00 <i>700</i>
	- Spray painting on affected & replace parts	1.0	800.00	800.00 <i>600</i>
				2,270.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

E. & O. E.

Total S\$: 7,629.12  
GST 7% S\$: 534.04  
Amount Due S\$: 8,163.16

  
for CITY AUTO PTE LTD