

ASS. REC. BY:

REF:

116 / 20007133/Ke

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____ City Ave

of _____

Insured: _____ 699N

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH1604K Yr Regn: 02, 18

Type: M.Car / M.Cycle / Bus Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Hrace c.c. 2982

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 55466 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: K01420 0228318

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: MITS/Rlm / STD A/Rlm or

Tyre Size: F: 195R15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 6 mm

L/Bal. 9 mm L/Bal. 6 mm

D.O.A. 6/7/20 D.O.I. 9/7/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/7 @ 4590.94 Confirmed

Date/Time, File Pass to?

☐ : Preil. Report☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation:

) \$ - RS. SI

) Fuel

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202007-000241(00)

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY #07-16

SINGAPORE 079120

Date : 08/07/2020

Vehicle No. : GBH1604K

Make/Model : TOYOTA HIACE

Mileage (km) : 0

Chassis No. : KDH201-0228318

Accident Date : 06/07/2020 00:00:00

Claim No. : SJL1283L

Reference : JO202007-0299

Policy No. : 5097962989-02

Contact : -

Fax No. : 6880 4838

Not with order

Recovery B4 paint

B4590.94

5 days

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	Tailgate	1.0	2,021.70	2,021.70	<i>By</i>
2	Tailgate lock	1.0	265.74	265.74	<i>By</i>
3	Tailgate lock cover	1.0	122.30	122.30	<i>By</i>
4	Tailgate logo	1.0	61.70	61.70	<i>By</i>
5	Tailgate emblem - Hiace	1.0	49.50	49.50	<i>By</i>
6	Tailgate emblem - super GL	1.0	43.67	43.67	<i>By</i>
7	Tailgate outer chrome moulding	1.0	240.71	240.71	<i>By</i>
8	Tailgate weatherstrip	1.0	402.70	402.70	<i>By</i>
9	Tailgate striker	1.0	122.47	122.47	<i>By</i>
10	Tailgate inner trim	1.0	298.40	298.40	<i>By</i>
11	Rear bumper	1.0	396.90	396.90	<i>By</i>
12	Rear bumper retainer	2.0	40.33	80.66	<i>By</i>
13	Rear Bumper clips	12.0	4.21	50.52	<i>By</i>
14	Rear keyless entry antennae	1.0	212.67	212.67	<i>By</i>
15	Rear step panel	1.0	360.98	360.98	<i>By</i>
16	Rear end panel outer	1.0	315.95	315.95	<i>By</i>
17	Rear end panel inner	1.0	891.75	891.75	<i>By</i>
18	Rear end panel top garnish	1.0	178.30	178.30	<i>By</i>
19	Tail lamp	2.0	332.75	665.50	<i>By</i>
20	Tail lamp lower cover	2.0	141.66	283.32	<i>By</i>

List Total :

7,065.44

25% Discount S\$

1,766.32

5,299.12

SPECIAL NET :

1	Tailgate sticker - 70 Km/h	1.0	10.00	10.00	<i>By</i>
2	Tailgate sticker 6 pax	1.0	10.00	10.00	<i>By</i>
3	Glass sealant	1.0	40.00	40.00	<i>By</i>

SPECIAL NET Total S\$:

60.00

LABOUR :

* To remove and refit rear windscreen glass	1.0	100.00	100.00	<i>By</i>
* To remove and refit rear trims and upholstery	1.0	120.00	120.00	<i>By</i>
* To check wiring and lighting	1.0	50.00	50.00	<i>By</i>
* To spray rubberized under-coating	1.0	150.00	150.00	<i>By</i>

CONTINUE NEXT PAGE

2960.94
~~2968.44~~
1630
~~4588.44~~



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202007-000241(00)

Date : 08/07/2020

Vehicle No. : GBH1604K

Make/Model : TOYOTA HIACE

Mileage (km) : 0

Chassis No. : KDH201-0228318

Accident Date : 06/07/2020 00:00:00

Claim No. : SJL1283L

Reference : JO202007-0299

Policy No. : 5097962989-02

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78

SHENTON WAY #07-16

SINGAPORE 079120

Contact : -

Fax No. : 6880 4838

S/No	Particular	Quantity	Unit Price	Amount S\$
	* To supply panel sealant and to seal off all weld spot seam and gaps	1.0	150.00	150.00 300
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	900.00	900.00 700
	- Spray painting on affected & replace parts	1.0	800.00	800.00 600
				<u>2,270.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

E. & O. E.

Total S\$: 7,629.12

GST 7% S\$: 534.04

Amount Due S\$: 8,163.16

for CITY AUTO PTE LTD