



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

AIG ASIA PACIFIC INSURANCE PTE. LTD

NO. 78
SHENTON WAY #07-16
SINGAPORE 079120

Contact :-

Fax No. : 6880 4838

Not Authorized
Recovery B4paint

Estimate : QUOT202007-000241(00)

Date : 08/07/2020
Vehicle No. : GBH1604K
Make/Model : TOYOTA HIACE

Mileage (km) : 0
Chassis No. : KDH201-0228318
Accident Date : 06/07/2020 00:00:00
Claim No. : SJL1283L
Reference : JO202007-0299
Policy No. : 5097962989-02

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Tailgate	1.0	2,021.70	2,021.70 ✓
2	Tailgate lock	1.0	265.74	265.74 ✓
3	Tailgate lock cover	1.0	122.30	122.30 ✓
4	Tailgate logo	1.0	61.70	61.70 ✓
5	Tailgate emblem - Hiace	1.0	49.50	49.50 ✓
6	Tailgate emblem - super GL	1.0	43.67	43.67 ✓
7	Tailgate outer chrome moulding	1.0	240.71	240.71 ✓
8	Tailgate weatherstrip	1.0	402.70	402.70 ✓
9	Tailgate weatherstrip	1.0	122.47	122.47 ✓
10	Tailgate striker	1.0	298.40	298.40 ✓
11	Tailgate inner trim	1.0	396.90	396.90 ✓
12	Rear bumper	2.0	40.33	80.66 ✓
13	Rear bumper retainer	12.0	4.21	50.52 ✓
14	Rear Bumper clips	1.0	212.67	212.67 ✓
15	Rear keyless entry antenne	1.0	360.98	360.98 ✓
16	Rear step panel	1.0	315.95	315.95 ✓
17	Rear end panel outer	1.0	891.75	891.75 ✓
18	Rear end panel inner	1.0	178.30	178.30 ✓
19	Rear end panel top garnish	2.0	332.75	665.50 X
20	Tail lamp	2.0	141.66	283.32 X
	Tail lamp lower cover			
	List Total :			7,065.44
	25% Discount S\$			1,766.32
				5,299.12
SPECIAL NET :				
1	Tailgate sticker - 70 Km/h	1.0	10.00	10.00 ✓
2	Tailgate sticker 6 pax	1.0	10.00	10.00 ✓
3	Glass sealant	1.0	40.00	40.00 ✓
	SPECIAL NET Total S\$:			60.00
LABOUR :				
	* To remove and refit rear windscreen glass	1.0	100.00	100.00 ✓
	* To remove and refit rear trims and upholstery	1.0	120.00	120.00 601
	* To check wiring and lighting	1.0	50.00	50.00 201
	* To spray rubberized under-coating	1.0	150.00	150.00 601

CONTINUE NEXT PAGE

Page 1 of 2