HUA CHIN (2000) TRADING MOTOR SERVICE CENTRE

50, Bukit Batok Street 23, #02-02 Midview Building, Singapore 659578 TEL: 6896 6619

Date:

20.07.2020

/S: China Taiping Insurance (S) Pte Ltd

3 Anson Rd, #16-00 Springleaf Tower, 079909

Date: 20.07.2020

Veh Reg No: FBF2471E

Make/Model: YAMAHA / T135

Chasis No: 5YP012761

Engine No: 5YP012761

Reg Date: 28-Mar-11 one: 6389 6111 ur Ref No: FBF2471E Third-Party aim Type : cident Date : 23.06.2020 10:30 HRS Veh Reg No: SMR9403M 28-Mar-11 Reg Date :

	Description	Estimate Repair Cost to Vehicle No : FBF2471E Scription Quantity			Amount		
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23	Balancer SCT Handle Bar X SVC Steering Cone nec Radiator bt Cover Set Cra Handle Bar Bracket X SVC Sport Rim repair Rim Shaft SCT Under Bracket bt Fork bt Head Light X SVC Gear Lever bt Gear Lever Shaft bt Engine Oil nec Gasket nec Lever bt Footrest SCT Coolant nec Pillion Footrest SCT Footrest Bracket bt Brake Disc (Front) X SVC Foot Brake Pedal SCT Exhaust Pelpe SCT	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis			\$75.00 \$95.00 X \$105.00 \$155.00 \$450.00 \$75.00 X \$450.00 X \$25.00 \$285.00 \$250.00 \$85.00 X \$45.00 \$45.00 \$45.00 \$45.00 \$48.00 \$85.00 \$20.00 \$48.00 \$70.00 \$85.00 X	2231 10% 2007.90	
24 25 26 27	Side Stand X SVC Cdi Unit X SVC Meter X SVC Brake Pump X SVC	Third party survey is on a No illegal modification(s) is Supplementary item(s) mu is subject to final approval Acknowledged by Repairer Signature: Date:	"Without Prejudice" basis s allowed st be resurveyed and	Less 10% Total	\$125.00 X \$125.00 X \$185.00 X \$95.00 X \$3,464.00 \$3,464.00 \$3,117.60		
28 29	S/NETT ITEMS Rear Box SCT/ Rear Box Bracket bro/				\$120.00 \$75.00 \$195.00	195	
30 31 32 33 34 35	Towing Fee To provide labour charges, work To align main body frame. To conduct wheel alignments. To spray painting on affected are To check eletrical wiring.	man ship to dismatle above dama ea.	ge parts. 2007.90 195.00 810.00 3012.90		\$80.00 \$800.00 \$450.00 \$180.00 \$350.00 \$80.00 \$1,940.00	810	
	4 repair days		20% 2410.32 L/S - 2400	Total rep a	\$5,252.60 air limit - 1800		