

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Jul 2020		28 Sep 2020 16:18 Edit Adj Rpt	S\$1,800.00 Edit Estimates	S\$1,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	RWAVE PTE. LTD, Co. Reg. No.: 201909822G								
Vehicle Reg. No.:	FBF2471E	Date of Loss:	23/06/2020 10:00 - :59 [110 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D202234/C02	Policy/Cover Note No.:	DMHCSNW00000682000						
Vehicle Reg. No. (Insured):	SMR9403M	Policy No. (Claimant):	5108520408-01 (TP)						
		Excess:	S\$0.00						
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 07/10/2020]								
Adj Asg. Remarks:	third party choose Marcus Chua as SJE. Survey revert								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBF2471E (SNM20D202234/C02)**
[SMR9403M]

TP

RWAVE PTE. LTD

Jun 23 2020 10:00AM

[0]

Hua Chin (2000) Trading Motor Service Centre

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	VAC (Bukit Batok)		Thumbnail Print
1	29/06/20 18:14	Accident Statement		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	02/10/20 11:03	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page ▼	☒
No	Finalized On	VAC (Bukit Batok)		Thumbnail Print
1	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
2	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
3	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
4	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
5	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
6	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
7	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
8	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
9	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
10	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
11	29/06/20 18:13	Accident Photo [Linked Accident Report Documents]		Load JPG ☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	05/10/20 10:47	General View		Load PDF
2	05/10/20 10:48	Reinspection Photo		Load PDF
Documentation			1 per page ▼	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	28/09/20 16:19	Pre-Repair Survey		Load PDF
No	Finalized On	VAC (Bukit Batok)		Thumbnail Print
1	29/06/20 18:14	Sketch Plan [Linked Accident Report Documents]		Load TIF
2	29/06/20 18:14	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF
3	29/06/20 18:14	Sketch Plan #3 [Linked Accident Report Documents]		Load TIF
4	29/06/20 18:14	Sketch Plan #4 [Linked Accident Report Documents]		Load TIF
5	29/06/20 18:14	Sketch Plan #5 [Linked Accident Report Documents]		Load TIF

Linked Accident Report Documents

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	VAC (Bukit Batok)		Thumbnail Print
1	29/06/20 18:14	Accident Statement		Load HTM

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
Photos/Images			3 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	29/06/20 18:13	Accident Photo	Load JPG	☒
2	29/06/20 18:13	Accident Photo	Load JPG	☒
3	29/06/20 18:13	Accident Photo	Load JPG	☒
4	29/06/20 18:13	Accident Photo	Load JPG	☒
5	29/06/20 18:13	Accident Photo	Load JPG	☒
6	29/06/20 18:13	Accident Photo	Load JPG	☒
7	29/06/20 18:13	Accident Photo	Load JPG	☒
8	29/06/20 18:13	Accident Photo	Load JPG	☒
9	29/06/20 18:13	Accident Photo	Load JPG	☒
10	29/06/20 18:13	Accident Photo	Load JPG	☒
11	29/06/20 18:13	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	29/06/20 18:14	Sketch Plan	Load TIF	
2	29/06/20 18:14	Sketch Plan #2	Load TIF	
3	29/06/20 18:14	Sketch Plan #3	Load TIF	
4	29/06/20 18:14	Sketch Plan #4	Load TIF	
5	29/06/20 18:14	Sketch Plan #5	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20007142/R1TF3S2**Date:** 05/10/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00000682000
Claimant Vehicle No :	FBF2471E	Insured Vehicle No :	SMR9403M
Date of Loss:	23/06/2020	Nature of Claim:	TP
		Claim No:	SNM20D202234/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBF2471E	Engine No:	5YP012761
Make & Model:	YAMAHA T135, 135cc	Chassis No:	5YP012761
Reg. Date:	28/03/2011 (Man. Year: 2010)	Odometer:	79280 km
Colour:	Red		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	90/80-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,312.60	2,202.90	1,109.70	33.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	810.00	1,130.00	58.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,252.60	3,012.90	2,239.70	42.64
Approved Total (Overridden) (\$\$)		1,800.00		
(\$\$)	5,252.60	1,800.00	3,452.60	65.73
+ GST 7.00/7.00% (\$\$)	367.68	126.00	241.68	65.73
Nett Amount (\$\$)	5,620.28	1,926.00	3,694.28	65.73

INSPECTION

Date of Assignment:	28/09/2020	
Date Inspected:	09/07/2020 Inspected At:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING Singapore 659578
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Oct 2020)	
Parts:	N/A	YAMAHA T135 135cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBF2471E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BALANCER	Scratched	75.00 FL	*75.00 FL
2	1		*HANDLE BAR	Serviceable	95.00 FL	*- FL
3	1		*STEERING CONE	Necessary	105.00 FL	*105.00 FL
4	1		*RADIATOR	Bent	155.00 FL	*155.00 FL
5	1		*SET COVER	Cracked	450.00 FL	*450.00 FL
6	1		*HANDLE BAR BRACKET	Serviceable	75.00 FL	*- FL
7	1		*SPORT RIM	Repair	450.00 FL	*- FL
8	1		*RIM SHAFT	Scratched	25.00 FL	*25.00 FL
9	1		*UNDER BRACKET	Bent	285.00 FL	*285.00 FL
10	2		*FORK	Bent	250.00 FL	*250.00 FL
11	1		*HEAD LIGHT	Serviceable	85.00 FL	*- FL
12	1		*GEAR LEVER	Bent	45.00 FL	*45.00 FL
13	1		*GEAR LEVER SHAFT	Bent	85.00 FL	*85.00 FL
14	1		*ENGINE OIL	Necessary	30.00 FL	*30.00 FL
15	1		*GASKET	Necessary	45.00 FL	*45.00 FL
16	1		*LEVER	Bent	48.00 FL	*48.00 FL
17	1		*FOOTREST	Scratched	85.00 FL	*85.00 FL
18	1		*COOANT	Necessary	20.00 FL	*20.00 FL
19	1		*PILLION FOOTREST	Scratched	48.00 FL	*48.00 FL
20	1		*FOOTREST BRACKET	Bent	70.00 FL	*70.00 FL
21	1		*BRAKE DISC (FRONT)	Serviceable	85.00 FL	*- FL
22	1		*FOOT BRAKE PEDAL	Scratched	60.00 FL	*60.00 FL
23	1		*EXHAUST PIPE	Scratched	350.00 FL	*350.00 FL
24	1		*SIDE STAND	Serviceable	38.00 FL	*- FL
25	1		*CDI UNIT	Serviceable	125.00 FL	*- FL
26	1		*METER	Serviceable	185.00 FL	*- FL
27	1		*BRAKE PUMP	Serviceable	95.00 FL	*- FL
28	1		*REAR BOX	Scratched	120.00 FS	*120.00 FS
29	1		*REAR BOX BRACKET	Broken	75.00 FS	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,659.00	2,426.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	346.40	223.10
Total Parts (\$\$)	3,312.60	2,202.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE.	New	80.00	40.00
2	TO PROVIDE LABOUR CHARGES, WORKMAN SHIP TO DISMANTLE ABOVE DAMAGE PARTS.	New	800.00	300.00
3	TO ALIGN MAIN BODY FRAME.	New	450.00	150.00
4	TO CONDUCT WHEEL ALIGNMENTS.	New	180.00	50.00
5	TO SPRAY PAINTING ON AFFECTED AREA.	New	350.00	250.00
6	TO CHECK ELECTRICAL WIRING.	New	80.00	20.00
Gross Labour Cost (S\$)			1,940.00	810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >